

\*Parts are subject to availability on a first come first serve basis. Prices displayed are with the discount applied and subject to change without notice.

This list was last updated 22.12.2022

| Material Part number (PNR) | Stock* | Discount (%) | Price (after discount)* |
|----------------------------|--------|--------------|-------------------------|
|                            | 50     |              |                         |
| EN6114-10Y36:I9005         | 10     | 20           | \$69.92                 |
| MBF2113S7-300:92215        | 150    | 20           | \$14.66                 |
| MS28774-130:96906          | 205    | 20           | \$0.22                  |
| NAS1156E15:80205           | 79     | 50           | \$2.41                  |
| NAS1921B04-07FC:80205      | 912    | 20           | \$1.54                  |
| NAS7403-2:80205            | 15     | 20           | \$0.11                  |
| NSA5356-10-30:F6198        | 28     | 50           | \$87.08                 |
| NSA5479BV3-11X:F6198       | 30     | 20           | \$1.66                  |
| NSA5488V7R19N:F6198        | 9      | 50           | \$20.21                 |
| ASNA3757G242408:F6198      | 70     | 20           | \$60.83                 |
| CR3553-6-08:11815          | 240    | 50           | \$2.57                  |
| DIN471-10X1:D8286          | 37     | 20           | \$0.80                  |
| HL112VF10-6:92215          | 7352   | 50           | \$7.28                  |
| MS16632-4043:96906         | 62     | 50           | \$0.46                  |
| MS20426DD4-10:96906        | 539    | 20           | \$3.24                  |
| NAS463XDD10:80205          | 225    | 50           | \$0.20                  |
| NAS8703A3:80205            | 45     | 50           | \$1.89                  |
| NSA5031-7-16:F6198         | 11     | 50           | \$8.94                  |
| ABS0060-114:FAPE3          | 8      | 50           | \$4.94                  |
| ABS0650-08:FAPE3           | 62164  | 50           | \$106.42                |
| ASNA2049DCJ3208:F6198      | 14     | 50           | \$0.02                  |
| MS3456KT24-10S:96906       | 54     | 30           | \$27.60                 |
| NSA5351-7-18:F6198         | 22     | 50           | \$26.09                 |
| NSA5356-10-15:F6198        | 109    | 50           | \$263.25                |
| NSA5479VHK4-6Y:F6198       | 59     | 50           | \$20.37                 |
| ABS0114T8-23:FAPE3         | 60     | 50           | \$5.52                  |
| DHS782-19-16:U1598         |        | 50           | \$0.48                  |
| EN2997SE01610F6:I9005      | 5      | 50           | \$57.96                 |
| EN6114L10X22:I9005         | 20     | 20           | \$481.23                |
| HLT924BV12-19:73197        | 165    | 50           | \$157.45                |
| MS51830-103L:96906         | 165    | 50           | \$1.98                  |
| NAS1351C4-12:80205         | 101    | 50           | \$1.02                  |
| NAS6204-56:80205           | 490    | 30           | \$2.40                  |
| NSA5031-3-54:F6198         | 55     | 20           | \$3.98                  |
| NSA5042C10-670:F6198       | 96     | 50           | \$74.25                 |
| E0545F21-35YA:F5442        | 5      | 20           | \$6.01                  |
| EN2997K62255MN:I9005       | 345    | 50           | \$49.54                 |
| HL10VF8-20:92215           | 4170   | 20           | \$3.73                  |
| MS16562-17:96906           | 1480   | 50           | \$0.08                  |
| MS21206-8:96906            | 50     | 50           | \$0.09                  |
| MS51021-57:96906           | 190    | 20           | \$1.79                  |
| NSA5089-4D14:F6198         | 5      | 50           | \$3.63                  |
| S64-2E370:K5640            | 17     | 50           | \$5.84                  |
| ABS0473-22:FAPE3           | 60     | 50           | \$35.96                 |
| ABS0785B114B:FAPE3         |        | 50           | \$3.71                  |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| ABS1295V3-1A01:FAPE3  | 52    | 50 | \$7.02   |
| AN316C5R:88044        | 735   | 50 | \$0.38   |
| ASNA0093-8-13:F6198   | 247   | 20 | \$6.68   |
| ASNA2051DCJ3611:F6198 | 290   | 50 | \$1.14   |
| DHS1674-2:U1598       | 397   | 20 | \$0.15   |
| LN9499M3X1-5DA2:D8442 | 587   | 50 | \$0.38   |
| MS21923-4:96906       | 50    | 20 | \$1.19   |
| NAS1101E06-6:80205    | 83    | 50 | \$0.53   |
| NAS1992T4PT:80205     | 450   | 20 | \$0.33   |
| ABS0584V15-09P:FAPE3  | 8     | 50 | \$94.71  |
| ASNA2557-07Y:F6198    | 35    | 50 | \$88.78  |
| EN6115T9-32:I9005     | 162   | 50 | \$9.89   |
| HL11VF8-20:92215      | 660   | 50 | \$2.58   |
| HST12AG5-7:73197      | 39    | 20 | \$1.89   |
| MS20426T8-15:96906    | 93    | 20 | \$1.99   |
| NAS1149F1890P:80205   | 40    | 50 | \$0.96   |
| NSA5379-20C:F6198     | 995   | 50 | \$4.14   |
| NSA932805-21A:F6198   | 42    | 20 | \$11.45  |
| ABS1418-12-34:FAPE3   | 18    | 50 | \$235.69 |
| ASNA2657V4-11:F6198   | 6     | 50 | \$6.19   |
| EN6114-7-7:I9005      | 131   | 20 | \$33.60  |
| HL410VF6-18:C4293     | 400   | 20 | \$0.76   |
| MS90707-4025:96906    | 379   | 20 | \$0.40   |
| NAS1102E06-12:80205   | 335   | 50 | \$1.21   |
| NAS1790C4R10:80205    | 990   | 50 | \$1.42   |
| NAS43HT4-48:80205     | 930   | 50 | \$0.66   |
| NSA5357-5-7:F6198     | 65    | 20 | \$2.75   |
| NSA5476VHK6-12:F6198  | 1122  | 50 | \$1.32   |
| BP258A2G1:15084       | 22    | 50 | \$43.45  |
| EN6081AD5-09:I9005    | 12190 | 50 | \$0.09   |
| EN6101D4-10-5:I9005   | 18780 | 50 | \$0.05   |
| EN6115K3X20:I9005     | 60    | 20 | \$10.75  |
| NAS8704-13:80205      | 38    | 50 | \$5.31   |
| ABS1088A01A01:FAPE3   | 218   | 50 | \$1.46   |
| ABS1244A02:FAPE3      | 22    | 50 | \$27.39  |
| ASNA2042-3-03:F6198   | 960   | 50 | \$0.41   |
| E0163D20-73X:F6198    | 47    | 20 | \$53.98  |
| EN6115K3X24:I9005     | 49    | 20 | \$12.39  |
| NAS1102V3-19A:80205   | 320   | 50 | \$3.35   |
| NAS1149CN949B:80205   | 25850 | 50 | \$0.04   |
| NSA5356-5-9:F6198     | 15    | 50 | \$28.39  |
| NSA5378-7A17:F6198    | 6     | 50 | \$9.12   |
| ASNA2001V3-17X:F6198  | 91    | 20 | \$17.03  |
| DHS781-11-16:U1598    | 585   | 50 | \$0.38   |
| EN3646RS01006DN:I9005 | 10    | 50 | \$20.59  |
| EN3646RS61419AW:I9005 | 50    | 20 | \$4.83   |
| NAS1153-22:80205      | 2934  | 50 | \$0.23   |
| NAS1352-08H20P:80205  | 190   | 50 | \$0.95   |
| NAS1763D050505:80205  | 44    | 50 | \$59.11  |
| NSA5319C10-18:F6198   | 108   | 50 | \$3.56   |

|                       |      |    |          |
|-----------------------|------|----|----------|
| NSA5476VHK5-14:F6198  | 2150 | 50 | \$0.75   |
| NSA5478VHK10-17:F6198 | 8    | 50 | \$80.43  |
| SP42P:K7766           | 600  | 50 | \$0.69   |
| ABS0335-08-04:FAPE3   | 8    | 50 | \$43.56  |
| ABS1028D00AA498:FAPE3 | 6    | 50 | \$247.87 |
| AS21919WCH25:81343    | 10   | 50 | \$3.43   |
| E0486B05:F5442        | 24   | 50 | \$23.81  |
| NAS1738MW4-2:80205    | 450  | 20 | \$0.27   |
| NAS1802-3-13P:80205   | 780  | 30 | \$0.39   |
| NSA5101-005:F6198     | 13   | 50 | \$6.87   |
| NSA5359-8-32:F6198    | 3    | 50 | \$32.74  |
| ABS1004A10:FAPE3      | 8    | 50 | \$114.09 |
| ABS1708LJ0743:FAPE3   | 25   | 50 | \$225.10 |
| EN2997RS00803A6:I9005 | 8    | 50 | \$24.00  |
| EN6115K7-26:I9005     | 500  | 50 | \$4.87   |
| NAS1351-3H12P:80205   | 400  | 50 | \$1.32   |
| NAS602-18P:80205      | 854  | 50 | \$0.28   |
| NAS6206-22D:80205     | 260  | 30 | \$1.12   |
| NSA5121-08-070:F6198  | 50   | 50 | \$12.45  |
| NSA5121C04-140:F6198  | 31   | 50 | \$2.85   |
| NSA5398-6-18:F6198    | 58   | 50 | \$40.86  |
| NSA5476BV7-26:F6198   | 13   | 50 | \$22.04  |
| ABS0114T5D17:FAPE3    | 120  | 50 | \$2.84   |
| ABS1381-004LZ04:FAPE3 | 16   | 50 | \$37.75  |
| HL10V6-13:73197       | 183  | 50 | \$2.99   |
| HL410VF6-16:92215     | 130  | 20 | \$2.98   |
| MS21260S3RH:96906     | 29   | 50 | \$3.62   |
| NAS514P632-14P:80205  | 1923 | 50 | \$0.07   |
| NAS564-12:80205       | 1000 | 50 | \$15.08  |
| 15R10-1AC:D0680       | 625  | 50 | \$0.25   |
| 2600-9:K1678          | 187  | 50 | \$2.22   |
| ASNA2041D3-13:F6198   | 600  | 50 | \$1.18   |
| E0053R16B8SNF:F5442   | 95   | 20 | \$3.51   |
| HLT924BV14-13:73197   | 10   | 50 | \$209.07 |
| MS20426A5-10:96906    | 2200 | 20 | \$0.21   |
| MS51957-19:96906      | 9870 | 50 | \$0.20   |
| NAS1157E13:80205      | 278  | 50 | \$0.93   |
| NSA5487-7-20N:F6198   | 286  | 20 | \$15.92  |
| ABS0114V4-2Y:FAPE3    | 89   | 50 | \$46.19  |
| ABS1358-14-12B:FAPE3  | 91   | 50 | \$31.81  |
| CR3243-6-10:11815     | 200  | 50 | \$0.78   |
| DAN7-12-10X:D8518     | 84   | 50 | \$17.95  |
| E0053R22B55PXF:F5442  | 90   | 20 | \$4.26   |
| E0092-51-345NN:F5442  | 83   | 20 | \$1.15   |
| E0165D10A80X:F5442    | 5    | 20 | \$61.10  |
| E0617A21N:F5442       | 22   | 50 | \$4.99   |
| E0733-006E20AA:F6198  | 4    | 20 | \$226.86 |
| HLT912BV10-8:92215    | 506  | 20 | \$5.43   |
| NAS1160-6-35D:80205   | 21   | 50 | \$81.99  |
| NAS6705DU22:80205     | 200  | 50 | \$4.45   |



|                       |       |    |            |
|-----------------------|-------|----|------------|
| NSA5031-4D27:F6198    | 640   | 50 | \$0.66     |
| NSA5476BV5-14:F6198   | 686   | 50 | \$13.22    |
| NSA5516A43ND:F6198    | 500   | 30 | \$0.81     |
| ABS1343S20-04NF:FAPE3 | 24    | 50 | \$144.90   |
| EN6069KE5X06-5:I9005  | 178   | 50 | \$18.17    |
| EN6114B5Y18:I9005     | 22    | 30 | \$11.43    |
| HL410VF8-20:C4293     | 150   | 20 | \$1.21     |
| HL412VF10-15:C4293    | 583   | 50 | \$7.11     |
| HLT902BV12-17:92215   | 1     | 50 | \$28.69    |
| NAS1635-04-4:80205    | 25714 | 50 | \$0.06     |
| NAS6707U12:80205      | 86    | 50 | \$7.11     |
| NAS7203A2:80205       | 29    | 30 | \$34.50    |
| NSA5357-3-3:F6198     | 392   | 50 | \$1.24     |
| ASNA0097P5-12:F6198   | 6     | 20 | \$45.93    |
| EN6114K8Y22:I9005     | 5     | 20 | \$55.58    |
| EN6115-4Y8:I9005      | 125   | 50 | \$22.72    |
| MS9489-13:96906       | 691   | 50 | \$2.06     |
| NAS6704D23:80205      | 84    | 50 | \$4.84     |
| NSA5353-05A:F6198     | 1650  | 50 | \$0.12     |
| NSA5477VHK8-20:F6198  | 131   | 50 | \$63.03    |
| NSA933674B165:F6198   | 24    | 50 | \$1,433.75 |
| PE20001D04:F6087      | 4     | 20 | \$24.62    |
| ASNA3757E101004:F6198 | 8     | 20 | \$34.52    |
| EN2997RS61203BN:I9005 | 16    | 20 | \$8.12     |
| EN6114K6-26:I9005     | 386   | 50 | \$3.66     |
| HL633-5-7:92215       | 370   | 50 | \$2.55     |
| HLT901KN10-16:60516   | 25    | 50 | \$12.43    |
| MS9276-19:96906       | 129   | 50 | \$2.26     |
| NAS4403-5:80205       | 1050  | 50 | \$0.33     |
| NAS620C10:80205       | 9893  | 50 | \$0.05     |
| NAS624-14:80205       | 343   | 50 | \$2.04     |
| NAS6712DU60:80205     | 11    | 20 | \$11.97    |
| ABS0895-4-10:FAPE3    | 68    | 50 | \$5.30     |
| ASNA2050DCJ3236:F6198 | 894   | 50 | \$0.43     |
| EN6115K4X20:I9005     | 59    | 50 | \$26.01    |
| MS20392-1C7:96906     | 30    | 50 | \$1.26     |
| NSA5478BV10-18:F6198  | 1     | 50 | \$199.49   |
| NSA5516-07NJ:F6198    | 639   | 50 | \$0.52     |
| ASNA2314-6C13:F6198   | 29    | 20 | \$13.91    |
| DIN471-4X0-4:D8286    | 1350  | 50 | \$0.58     |
| EN6081D7-06:I9005     | 15727 | 50 | \$0.08     |
| EN6114K7-24:I9005     | 380   | 30 | \$2.60     |
| MS20253P2-625:96906   | 645   | 30 | \$0.38     |
| NAS514P1032-21:80205  | 1075  | 50 | \$0.35     |
| NAS6403A7:80205       | 312   | 50 | \$2.68     |
| NSA5399-5-22A:F6198   | 75    | 50 | \$15.45    |
| ABS0395T1-32:FAPE3    | 1     | 50 | \$36.80    |
| ABS0992B04:FAPE3      | 25    | 50 | \$6.16     |
| ABS1412EFE30:FAPE3    | 14    | 50 | \$39.79    |
| ASNA2001T4-5Y:F6198   | 72    | 20 | \$16.34    |

|                       |      |    |          |
|-----------------------|------|----|----------|
| ASNA2314-6-14:F6198   | 10   | 50 | \$43.56  |
| HL13VF8-16:92215      | 85   | 50 | \$1.63   |
| HL755VF6-9:92215      | 12   | 50 | \$15.97  |
| MBF2112S7-150:92215   | 20   | 20 | \$13.80  |
| NAS1004-1A:80205      | 212  | 50 | \$1.65   |
| NAS604-28P:80205      | 80   | 50 | \$0.86   |
| NSA5356-7-20:F6198    | 23   | 20 | \$32.23  |
| NSA5357-10-34:F6198   | 150  | 20 | \$21.39  |
| NSA5372E516C:8848B    | 790  | 30 | \$0.29   |
| NSA5483PN4-10:F6198   | 26   | 20 | \$8.85   |
| NSA855007-16:F6198    | 12   | 20 | \$67.50  |
| NSA934120-03:F6198    | 9    | 50 | \$47.78  |
| NSA935808-02:F6198    | 5600 | 50 | \$0.06   |
| PLT225-6-5:98524      | 10   | 50 | \$61.36  |
| 3TL946-8-17N:73197    | 4    | 50 | \$73.16  |
| ABS1700AF1014B:FAPE3  | 61   | 50 | \$166.53 |
| EN6101D6-04:I9005     | 1383 | 20 | \$0.19   |
| EN6101KE7-06:I9005    | 393  | 30 | \$13.29  |
| M25988-4-246:81349    | 6    | 75 | \$25.67  |
| MS21106-4:96906       | 50   | 20 | \$2.43   |
| NAS514P632-16P:80205  | 759  | 50 | \$0.05   |
| NAS6705U42:80205      | 17   | 50 | \$4.15   |
| NSA5121-05-060:F6198  | 100  | 50 | \$1.65   |
| NSA5379-14CW:F6198    | 403  | 20 | \$0.37   |
| NSA5477BV5-18:F6198   | 23   | 20 | \$14.55  |
| NSA5516C47ND:F6198    | 500  | 20 | \$0.37   |
| ABS0392-030-25:FAPE3  | 1284 | 50 | \$9.25   |
| ASNA2001V5-8X:F6198   | 15   | 20 | \$15.53  |
| EN2997S60803FN:I9005  | 16   | 50 | \$48.07  |
| HL110VF10-7:92215     | 969  | 50 | \$3.08   |
| MS21279-06:96906      | 480  | 50 | \$0.66   |
| MS3456L20-15P:96906   | 4    | 20 | \$15.03  |
| NAS1149E0832P:80205   | 2902 | 30 | \$0.13   |
| NAS6204-16D:80205     | 165  | 50 | \$0.83   |
| NAS6606-23:80205      | 261  | 50 | \$1.99   |
| NSA855113-69:F6198    | 5    | 50 | \$76.98  |
| EN2997RS00803BN:I9005 | 30   | 20 | \$4.89   |
| EN2997SE01415DN:I9005 | 2    | 20 | \$19.66  |
| HL410VF8-18:C4293     | 200  | 20 | \$1.45   |
| HST755CF6-6:73197     | 89   | 50 | \$2.22   |
| NSA5478BV4-18:F6198   | 704  | 50 | \$14.24  |
| HLT909PB8-18:92215    | 53   | 50 | \$51.05  |
| NAS1836-3-12M:80205   | 706  | 20 | \$0.51   |
| NAS6604D26:80205      | 50   | 30 | \$1.24   |
| NSA5089-3-3:F6198     | 284  | 20 | \$0.48   |
| NSA5480PN12-25X:F6198 | 1    | 50 | \$605.20 |
| ABS0269H06A08:FAPE3   | 99   | 50 | \$3.25   |
| ABS0578-10:FAPE3      | 9    | 50 | \$31.22  |
| ABS2267C130A:FAPE3    | 91   | 50 | \$3.58   |
| EN6114K12-20:I9005    | 100  | 20 | \$27.26  |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| EN6114T5X13:I9005     | 21    | 30 | \$23.05  |
| HL110VF8-20:92215     | 340   | 20 | \$40.41  |
| HL855VF6-11:92215     | 74    | 50 | \$15.83  |
| MS20392-2C7:96906     | 766   | 50 | \$0.47   |
| MS24665-26:96906      | 3440  | 20 | \$0.02   |
| MS90354U0506:96906    | 797   | 50 | \$0.80   |
| NSA931927-05:F6198    | 2660  | 20 | \$0.04   |
| ASNA2001T4-31:F6198   | 251   | 50 | \$13.09  |
| ASNA2041-4-14H:F6198  | 35    | 50 | \$2.09   |
| CR3253-4-05:11815     | 244   | 50 | \$0.65   |
| DAN380-01:D8518       | 291   | 20 | \$0.13   |
| EN3646A62419BN:I9005  | 13    | 30 | \$18.39  |
| EN6114L6Y16:I9005     | 49    | 20 | \$32.81  |
| MS35335-31:96906      | 9700  | 50 | \$0.01   |
| NAS1149CN516R:80205   | 15909 | 50 | \$0.11   |
| NAS1792A4-4:80205     | 467   | 20 | \$0.21   |
| NSA5031-4-2:F6198     | 4365  | 50 | \$4.63   |
| NSA5398-5A14A:F6198   | 7     | 20 | \$81.13  |
| NSA5476VHK5-8:F6198   | 570   | 50 | \$7.43   |
| ABS0114V6-6:FAPE3     | 95    | 50 | \$2.49   |
| ABS0548VHK4-04:FAPE3  | 480   | 50 | \$0.99   |
| ABS0678A03:FAPE3      | 248   | 50 | \$3.83   |
| AGS4717-306BS:U1653   | 4496  | 50 | \$0.07   |
| EN3645M0JL20BA:I9005  | 13    | 20 | \$9.65   |
| MBF2112S7-350:92215   | 8     | 50 | \$53.67  |
| NSA5031H8D26:F6198    | 7     | 50 | \$615.84 |
| NSA5356-7-32:F6198    | 100   | 50 | \$65.60  |
| NSA5368PD516C:F6198   | 3034  | 50 | \$0.12   |
| NSA5369PD616D:F6198   | 46    | 50 | \$3.00   |
| NSA5479VHK3-3X:F6198  | 610   | 50 | \$15.83  |
| NSA931325-100:F6198   | 1     | 50 | \$116.34 |
| AN565B6H4:88044       | 89    | 50 | \$12.73  |
| EN2997SE02212AN:I9005 | 97    | 20 | \$14.08  |
| EN6115B6-9:I9005      | 500   | 50 | \$1.65   |
| MS24693-28B:96906     | 12484 | 20 | \$0.01   |
| MS51963-244:96906     | 800   | 20 | \$0.20   |
| NAS1149V0332M:80205   | 180   | 50 | \$0.29   |
| NAS1193K6-2P:80205    | 24    | 20 | \$3.00   |
| NAS6206-18:80205      | 100   | 20 | \$0.77   |
| NAS6606-46:80205      | 249   | 50 | \$3.45   |
| NSA5478VHK6-16:F6198  | 82    | 50 | \$77.03  |
| AS21022:U1653         | 125   | 30 | \$1.15   |
| ASNA2050DCJ2425:F6198 | 12028 | 30 | \$0.01   |
| M85052-1-12:81349     | 15    | 20 | \$5.61   |
| MS20426D5-15:96906    | 87    | 50 | \$9.33   |
| NAS1154E4P:80205      | 341   | 50 | \$0.44   |
| AN737TW82:88044       | 25    | 50 | \$2.15   |
| DIN65399-3214BF:D8286 | 554   | 50 | \$1.03   |
| HLT912BV6-4:92215     | 500   | 50 | \$0.43   |
| MS20615-8M20:96906    | 70    | 30 | \$1.06   |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| MS35206-241:96906     | 3500  | 50 | \$0.07   |
| NAS1133E8P:80205      | 131   | 50 | \$0.90   |
| NAS6308U24:80205      | 300   | 20 | \$1.35   |
| NAS6604-27:80205      | 636   | 50 | \$0.53   |
| NSA5042C06-270:F6198  | 109   | 20 | \$3.46   |
| NSA5054-8:F6198       | 38    | 50 | \$21.48  |
| AS2811-10-017:U1653   | 174   | 20 | \$0.34   |
| ASNA0243A08036:F6198  | 13    | 50 | \$26.63  |
| ASNA2001T4-7Y:F6198   | 93    | 20 | \$14.01  |
| EN3646A00898CN:I9005  | 50    | 50 | \$17.19  |
| EN6114K7Y35:I9005     | 25    | 20 | \$69.71  |
| EN6114K9Y36:I9005     | 95    | 20 | \$14.40  |
| EN6115V5-29:I9005     | 234   | 20 | \$6.19   |
| MS16998-59:96906      | 45    | 50 | \$1.06   |
| MS21073-08:96906      | 542   | 50 | \$0.41   |
| MS21103-10:96906      | 84    | 20 | \$0.36   |
| MS21919WCG8:96906     | 70    | 50 | \$0.72   |
| NAS1149DN316J:80205   | 48600 | 50 | \$0.02   |
| NAS1352C08-20:80205   | 68    | 50 | \$0.72   |
| NAS1921C06S07:80205   | 89    | 50 | \$9.11   |
| NAS428-3-5:80205      | 475   | 50 | \$0.81   |
| NAS6203-28:80205      | 678   | 50 | \$1.00   |
| NSA5041VBV3-3:F6198   | 509   | 50 | \$0.45   |
| ABS0569-08:FAPE3      | 50    | 50 | \$93.76  |
| ASNA2726N4-9:F6198    | 69    | 30 | \$1.73   |
| EN3646A01832AY:I9005  | 19    | 50 | \$9.52   |
| MS21090-0622:96906    | 1539  | 20 | \$0.04   |
| MS21921-12D:96906     | 80    | 50 | \$4.34   |
| MS24674-7:96906       | 1020  | 50 | \$0.61   |
| NAS1802-4D11:80205    | 63    | 20 | \$2.20   |
| NSA5368PD1216D:F6198  | 374   | 50 | \$0.98   |
| NSA5478VHK12-22:F6198 | 100   | 50 | \$69.99  |
| ABS1238-26-15C:FAPE3  | 13    | 50 | \$2.54   |
| ABS1389T1610:FAPE3    | 10    | 50 | \$204.46 |
| E0052R20B41SXF:F5442  | 40    | 50 | \$22.95  |
| E0390DD02S1A00A:F5442 | 92    | 20 | \$3.65   |
| EN2997RS60803B8:I9005 | 1     | 50 | \$34.71  |
| EN6115K3X18:I9005     | 8     | 20 | \$12.02  |
| HLT901BV8-12:73197    | 309   | 50 | \$18.85  |
| MS20426AD2-3:96906    | 10500 | 20 | \$0.01   |
| MS25237-328:96906     | 2152  | 30 | \$0.24   |
| MS9593-006:96906      | 200   | 50 | \$1.58   |
| NAS1351N4-8:80205     | 330   | 20 | \$1.25   |
| NAS6603-44:80205      | 120   | 50 | \$1.96   |
| NAS6704HU28:80205     | 180   | 20 | \$0.44   |
| NSA5042E04-220:F6198  | 52    | 50 | \$4.35   |
| ABS1114E096E230:FAPE3 | 8     | 50 | \$33.54  |
| ABS1464T10:FAPE3      | 10    | 50 | \$174.26 |
| ABS2195-19:F6198      | 10    | 50 | \$3.25   |
| ABS5642AEL29-12:FAPE3 | 450   | 50 | \$3.83   |

|                       |        |    |          |
|-----------------------|--------|----|----------|
| ASNA0141-9-10:F6198   | 12     | 50 | \$169.47 |
| ASNA2001V4-22:F6198   | 211    | 50 | \$3.16   |
| DAN7-6-13Y:D8518      | 110    | 50 | \$1.40   |
| HL21-5-3:92215        | 500    | 50 | \$4.72   |
| HST803CG6-9:73197     | 31     | 50 | \$137.33 |
| MS20664C2:96906       | 1010   | 50 | \$0.31   |
| NAS1352N08-10:80205   | 337    | 50 | \$0.47   |
| NSA5353D18B:F6198     | 21     | 50 | \$2.55   |
| S64-2Q250:K5640       | 57     | 20 | \$2.00   |
| ASNA2026V5-14:F6198   | 4      | 20 | \$15.64  |
| E0459-501A:F5442      | 54     | 20 | \$32.20  |
| EN6114-7-24:I9005     | 475    | 50 | \$7.21   |
| MS21059L8:96906       | 495    | 50 | \$20.92  |
| MS51861-24:96906      | 16500  | 50 | \$0.03   |
| NAS1097AD4-2:80205    | 6300   | 50 | \$0.01   |
| NAS1097D4-20:80205    | 2940   | 50 | \$0.04   |
| NSA5153V9-20:F6198    | 5      | 20 | \$24.19  |
| NSA5477BV10-29:F6198  | 13     | 50 | \$73.27  |
| NSA5478VHK5-15:F6198  | 1535   | 50 | \$15.35  |
| NSA5516CA03ND:F6198   | 1840   | 50 | \$0.48   |
| ABS0255-6-500Z:FAPE3  | 250    | 50 | \$2.96   |
| ABS0853-6-042:FAPE3   | 629    | 50 | \$41.88  |
| ABS0951C3LM008:FAPE3  | 17     | 50 | \$90.30  |
| AN500A6-10:88044      | 1157   | 50 | \$0.20   |
| AS21519:U1653         | 6      | 50 | \$8.52   |
| HLT926AP6-5:92215     | 400    | 20 | \$1.90   |
| L21217036015DCJ:F0111 | 1660   | 20 | \$0.41   |
| MS20426AD4-4:96906    | 115773 | 50 | \$0.02   |
| MS20426D3-6:96906     | 24800  | 50 | \$0.02   |
| MS21141-0502:96906    | 6      | 50 | \$9.80   |
| NAS1097D5-4:80205     | 20759  | 50 | \$0.02   |
| NAS1104-10:80205      | 1160   | 50 | \$0.34   |
| NSA5478BV4-3:F6198    | 950    | 20 | \$2.67   |
| ASNA2041-2-03:F6198   | 70     | 50 | \$0.86   |
| E0186R18S31-01F:F5442 | 97     | 50 | \$18.63  |
| EN6101KE8-12:I9005    | 227    | 20 | \$0.42   |
| EN6114T7X28:I9005     | 31     | 50 | \$42.48  |
| NAS1101E08-16P:80205  | 350    | 50 | \$0.98   |
| NAS6708DU34:80205     | 1      | 20 | \$206.69 |
| NSA5372PD916D:F6198   | 99     | 50 | \$0.41   |
| NSA5477VHK4-13:F6198  | 775    | 20 | \$5.20   |
| NSA5482PN10-34:F6198  | 89     | 50 | \$74.52  |
| ABS1128A01A01:FAPE3   | 9      | 50 | \$319.75 |
| ASNA2016T3-3:F6198    | 1798   | 30 | \$0.86   |
| ASNA2041-3-05H:F6198  | 20     | 50 | \$2.95   |
| ASNA2586-44-018:F6198 | 250    | 50 | \$12.57  |
| CR7774S05-03:11815    | 879    | 20 | \$2.59   |
| EN6114K9-32:I9005     | 61     | 50 | \$9.26   |
| L21215048025DEJ:F0111 | 1430   | 20 | \$0.28   |
| MS51862-18:96906      | 834    | 50 | \$0.34   |



|                       |      |    |         |
|-----------------------|------|----|---------|
| NAS1727K8E:80205      | 23   | 50 | \$30.40 |
| NAS7503-3:80205       | 1008 | 20 | \$0.24  |
| NSA5039-08-4:F6198    | 1208 | 50 | \$0.38  |
| NSA5479VHK6-16Y:F6198 | 70   | 50 | \$46.65 |
| NSA855116-5D:F6198    | 8    | 50 | \$10.81 |
| NSA938152SA1202:F6198 | 736  | 20 | \$0.19  |
| ABS0696X2-2-48:FAPE3  | 10   | 50 | \$13.98 |
| ABS1475-03:FAPE3      | 24   | 50 | \$9.73  |
| EN2997KE3N12:I9005    | 99   | 50 | \$41.63 |
| EN3646A61808AW:I9005  | 26   | 20 | \$7.62  |
| EN6114B4E17:I9005     | 183  | 50 | \$2.33  |
| MS20470D7-10:96906    | 7274 | 50 | \$0.05  |
| MS21915J6-5:96906     | 100  | 20 | \$18.07 |
| NAS1303-16D:80205     | 825  | 20 | \$0.19  |
| NAS6605-34:80205      | 100  | 50 | \$1.64  |
| NSA5042-07-275:F6198  | 63   | 50 | \$5.92  |
| NSA5177-10:F6198      | 62   | 50 | \$7.55  |
| NSA5306-10:F6198      | 31   | 50 | \$28.82 |
| NSA937901M16-03:F6198 | 11   | 50 | \$10.08 |
| ASNA0033H112:F6198    | 95   | 50 | \$2.90  |
| ASNA2041-2-02:F6198   | 105  | 50 | \$0.83  |
| DIN933M4X12A2:D8286   | 920  | 50 | \$18.58 |
| EN3545E01FXA26B:I9005 | 3    | 50 | \$28.00 |
| EN6114T6-4:I9005      | 587  | 20 | \$1.90  |
| MS28775-345:96906     | 160  | 50 | \$0.83  |
| MS51861-39:96906      | 1755 | 50 | \$0.08  |
| MS9557-27:96906       | 124  | 50 | \$7.99  |
| NAS1474R4K:80205      | 36   | 50 | \$17.51 |
| NSA5477BV3-10:F6198   | 740  | 50 | \$1.80  |
| NSA5477BV5-19:F6198   | 3    | 50 | \$74.83 |
| NSA840003T075:F6198   | 21   | 50 | \$13.30 |
| TLN1000L3:92215       | 1750 | 20 | \$0.21  |
| ASNA2001T4-9Y:F6198   | 56   | 30 | \$24.71 |
| E0186R14S15-09:F5442  | 14   | 50 | \$12.61 |
| EN6115T4-21:I9005     | 300  | 20 | \$1.96  |
| MS20615-3M7:96906     | 923  | 20 | \$0.03  |
| MS21087-08:96906      | 1720 | 50 | \$0.72  |
| MS21233-6:96906       | 15   | 50 | \$28.77 |
| NAS1101V3-18A:80205   | 774  | 20 | \$1.44  |
| NAS6204-27:80205      | 227  | 50 | \$0.60  |
| NAS6205-3:80205       | 113  | 50 | \$0.53  |
| NAS6605-30:80205      | 134  | 50 | \$4.75  |
| NAS6703D3:80205       | 1031 | 50 | \$1.26  |
| NAS6705DU19:80205     | 292  | 50 | \$2.52  |
| NAS77-3-009:80205     | 27   | 20 | \$2.56  |
| NSA5042E08-614:F6198  | 100  | 50 | \$12.28 |
| NSA5089-5D17:F6198    | 112  | 20 | \$2.87  |
| NSA5089V4-8:F6198     | 475  | 30 | \$0.89  |
| NSA5353-03A:F6198     | 270  | 50 | \$1.23  |
| NSA5356-5-20:F6198    | 110  | 50 | \$37.46 |

|                       |       |    |          |
|-----------------------|-------|----|----------|
| NSA5398-5-20A:F6198   | 8     | 20 | \$93.48  |
| NSA5479VHK3-9Y:F6198  | 60    | 20 | \$274.47 |
| NSA5479VHK8-18X:F6198 | 53    | 50 | \$23.09  |
| ABS0112-32-05:FAPE3   | 1376  | 50 | \$0.29   |
| ABS0213-6-6:FAPE3     | 6     | 50 | \$7.87   |
| EN6114-4Y6:I9005      | 94    | 50 | \$76.38  |
| EN6115-10X42:I9005    | 38    | 20 | \$195.83 |
| MS28775-140:96906     | 1050  | 20 | \$0.74   |
| MS9489-04:96906       | 28    | 50 | \$1.92   |
| NAS1635-06-5:80205    | 24739 | 50 | \$0.09   |
| NAS6305U8:80205       | 948   | 50 | \$6.29   |
| NSA5476VHK5-7:F6198   | 85    | 50 | \$1.49   |
| AS62207:U1653         | 41    | 50 | \$13.08  |
| ASNA0082A206Y:F6198   | 297   | 50 | \$3.79   |
| HL856BJ10-13:73197    | 13    | 50 | \$35.52  |
| HLT856PB16-36:F0188   | 5     | 20 | \$29.89  |
| NAS1201C10A5A:80205   | 109   | 20 | \$1.82   |
| NAS1399M6-3:80205     | 61    | 50 | \$2.32   |
| NAS6404-12:80205      | 100   | 20 | \$12.08  |
| NSA55110-7:F6198      | 532   | 50 | \$1.55   |
| ASNA2151-13:F6198     | 50    | 50 | \$35.80  |
| CR3253-6-10:11815     | 260   | 20 | \$3.50   |
| EN6114-12Y40:I9005    | 87    | 50 | \$141.35 |
| EN6115-8-18:I9005     | 226   | 50 | \$16.61  |
| HL20PB8-5:92215       | 860   | 50 | \$0.93   |
| M25988-4-043:81349    | 200   | 50 | \$3.43   |
| MS21250-08042:96906   | 170   | 20 | \$85.15  |
| MS21916-4-2R:96906    | 76    | 50 | \$43.79  |
| NAS1100E08-14:80205   | 24600 | 20 | \$0.21   |
| NAS1304-2H:80205      | 24    | 20 | \$1.18   |
| NAS514P1032-32:80205  | 810   | 50 | \$0.82   |
| NAS561F2-9:80205      | 611   | 50 | \$1.44   |
| NSA8143-04XRK:F6198   | 100   | 20 | \$61.33  |
| ABS0787D57C:FAPE3     | 7     | 50 | \$9.66   |
| ASNA2001V5-7:F6198    | 268   | 20 | \$23.03  |
| DAN6-10-9X:D8518      | 208   | 50 | \$2.01   |
| DAN80-3-460:D8518     | 67    | 20 | \$7.86   |
| EN2550-032005:I9005   | 18216 | 50 | \$0.02   |
| EN6114K9X14:I9005     | 80    | 50 | \$124.41 |
| MS21093-0834:96906    | 648   | 50 | \$0.68   |
| MS21140U0603PW:96906  | 195   | 20 | \$3.98   |
| MS27183-6:96906       | 8600  | 50 | \$0.34   |
| MS90353-0611:96906    | 163   | 20 | \$4.19   |
| NAS6304-4H:80205      | 100   | 50 | \$8.24   |
| NSA5359-4-6:F6198     | 105   | 50 | \$37.70  |
| NSA5479BV5-22X:F6198  | 11    | 20 | \$78.42  |
| NSA938925BMS:F6198    | 28    | 50 | \$96.37  |
| ABS0581V16-12P:FAPE3  | 5     | 50 | \$29.33  |
| ASNA2392-2-05:F6198   | 643   | 30 | \$1.56   |
| EN6114-4Y5:I9005      | 38    | 20 | \$5.13   |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| MS20470AD5-14:96906   | 2295  | 50 | \$0.05   |
| MS90354-0502:96906    | 135   | 50 | \$1.74   |
| NAS6205-10D:80205     | 460   | 50 | \$2.95   |
| NSA5358-4-7:F6198     | 144   | 20 | \$39.49  |
| NSA5476BV3-4:F6198    | 1214  | 50 | \$22.02  |
| NSA5516A13NF:F6198    | 349   | 20 | \$2.45   |
| ABS0479-16:FAPE3      | 14    | 50 | \$185.91 |
| EN6069T5X08:I9005     | 124   | 20 | \$41.93  |
| EN6114-16X56:I9005    | 4     | 50 | \$427.54 |
| EN6114-5Y7:I9005      | 65    | 20 | \$82.13  |
| EN6115T8-14:I9005     | 80    | 30 | \$8.44   |
| HL410VF6-14:92215     | 897   | 20 | \$14.89  |
| HLT900BV6-7:73197     | 1740  | 20 | \$20.32  |
| HLT900BV8-8:92215     | 950   | 50 | \$23.92  |
| HLT908PB6-3:F0188     | 16    | 20 | \$11.69  |
| MS24693C295:96906     | 413   | 50 | \$0.31   |
| MS27039-4-29:96906    | 542   | 50 | \$0.87   |
| NAS43DD4-20FC:80205   | 100   | 20 | \$10.69  |
| NAS561C4-10:80205     | 4910  | 50 | \$0.52   |
| NSA5042-06-300:F6198  | 428   | 50 | \$41.20  |
| NSA5120U7-040:F6198   | 48    | 20 | \$27.88  |
| NSA5121C07-275:F6198  | 21    | 20 | \$33.44  |
| NSA5191-2V5:F6198     | 67    | 20 | \$26.24  |
| NSA5516CA26NJ:F6198   | 1000  | 20 | \$0.86   |
| EN2997RS61610BN:I9005 | 12    | 20 | \$52.36  |
| EN6046AN06ER:I9005    | 10    | 50 | \$28.43  |
| EN6069KE6-06-5:I9005  | 11732 | 50 | \$0.21   |
| HL855VF10-15:C4293    | 174   | 50 | \$7.80   |
| MS21318-7:96906       | 2700  | 20 | \$0.09   |
| NSA5159-39:F6198      | 20    | 50 | \$34.39  |
| NSA5454-18RH01:F6198  | 29    | 50 | \$285.54 |
| NSA5516CA05NJ:F6198   | 1400  | 20 | \$0.55   |
| ABS1656AA1-02:FAPE3   | 4     | 50 | \$22.00  |
| AN320-9:88044         | 140   | 50 | \$2.25   |
| HL112VF10-11:92215    | 13    | 50 | \$29.34  |
| HL755VF5-6:92215      | 70    | 20 | \$0.45   |
| MS27595-028:96906     | 795   | 30 | \$1.37   |
| MS28775-021:96906     | 1117  | 20 | \$0.31   |
| NAS1611-328:80205     | 18    | 50 | \$1.86   |
| NAS1836C3-43:80205    | 276   | 50 | \$1.77   |
| NAS6604-14X:80205     | 54    | 50 | \$84.43  |
| NAS6703HU7:80205      | 343   | 20 | \$1.97   |
| NSA5476VHK5-13:F6198  | 223   | 50 | \$1.49   |
| ASNA2722F3-22:F6198   | 231   | 20 | \$4.07   |
| DAN8-8-12Y:D8518      | 560   | 50 | \$1.10   |
| EN3645K6GL20BA:I9005  | 24    | 20 | \$85.78  |
| NAS1154E16:80205      | 287   | 50 | \$1.76   |
| NAS1306-24:80205      | 45    | 50 | \$6.07   |
| NAS1669-3L5:80205     | 694   | 50 | \$4.40   |
| NAS1762D0808:80205    | 50    | 50 | \$247.67 |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| NAS501-3-6A:80205     | 110   | 20 | \$1.56   |
| NSA5482PN4-7:F6198    | 9     | 20 | \$578.69 |
| ABS0059-257:FAPE3     | 8     | 50 | \$18.61  |
| ABS1381-03F1010:FAPE3 | 19    | 50 | \$99.82  |
| AN3C6A:88044          | 829   | 50 | \$0.91   |
| BACW10BP12APU:81205   | 107   | 20 | \$2.73   |
| DAN6-8-6Y:D8518       | 1284  | 50 | \$0.53   |
| EN6115B2E11:I9005     | 540   | 50 | \$1.56   |
| EN6115V5-30:I9005     | 372   | 20 | \$12.51  |
| HLT902BV10-10:73197   | 4     | 50 | \$44.84  |
| MS16997-11:96906      | 587   | 20 | \$0.48   |
| NAS1321AD8E21:80205   | 10566 | 50 | \$0.21   |
| NAS623-3-24:80205     | 2360  | 50 | \$0.21   |
| NAS6704HU19:80205     | 107   | 50 | \$6.10   |
| NSA5152T3:F6198       | 52    | 50 | \$31.03  |
| NSA5483PN12-20:F6198  | 3     | 20 | \$747.20 |
| NSA855154-10C:F6198   | 91    | 30 | \$145.02 |
| E0466TS3001:F6198     | 43    | 50 | \$78.54  |
| MS90353U1012:96906    | 386   | 20 | \$49.08  |
| NAS1790-4R20X:80205   | 27    | 20 | \$73.74  |
| NSA5399-5-16:F6198    | 179   | 50 | \$52.49  |
| ASNA2042-5-08H:F5442  | 1255  | 20 | \$3.33   |
| ASNA2380A3-9:F6198    | 241   | 50 | \$36.34  |
| DAN7-10-20X:D8518     | 59    | 50 | \$249.47 |
| EN6115V4-26:I9005     | 505   | 20 | \$10.90  |
| HL413VF10-15:C4293    | 6     | 20 | \$20.71  |
| MS15795-810:96906     | 2400  | 50 | \$0.16   |
| NAS1921M05S09WU:80205 | 426   | 20 | \$5.08   |
| NSA5516C04NJ:F6198    | 731   | 20 | \$1.02   |
| ASNA0032H210:F6198    | 18    | 50 | \$24.20  |
| EN3645M0DN19AN:I9005  | 27    | 50 | \$29.46  |
| EN6081KE5-04:I9005    | 382   | 50 | \$8.83   |
| HL10VF8-24:92215      | 470   | 50 | \$5.85   |
| NAS1151-15:80205      | 63    | 50 | \$39.33  |
| NAS6206-34:80205      | 55    | 50 | \$3.64   |
| NAS6603-11X:80205     | 73    | 50 | \$115.52 |
| NAS6603-14X:80205     | 18    | 20 | \$66.51  |
| NAS6608-3:80205       | 75    | 50 | \$3.09   |
| NSA5305-14:F6198      | 89    | 30 | \$13.11  |
| AN3CH3A:88044         | 39    | 50 | \$1.40   |
| DAN239-20:D8518       | 23    | 50 | \$9.32   |
| EN6114-12Y42:I9005    | 244   | 50 | \$76.84  |
| EN6114T6-5:I9005      | 98    | 20 | \$30.56  |
| MS15795-808:96906     | 10000 | 50 | \$0.10   |
| MS51861-36:96906      | 10150 | 50 | \$0.09   |
| NAS1102-08-28:80205   | 1043  | 50 | \$0.98   |
| NAS1790C3R8Y:80205    | 90    | 50 | \$124.50 |
| NAS6603D20:80205      | 195   | 50 | \$3.50   |
| NAS6704DU17:80205     | 1951  | 50 | \$4.30   |
| NAS6704U9Y:80205      | 76    | 20 | \$66.63  |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| NSA5478VHK9-21:F6198  | 9     | 50 | \$388.83 |
| ABS1418K7Y20:FAPE3    | 166   | 50 | \$37.72  |
| AN919-2:88044         | 27    | 20 | \$10.98  |
| ASNA0096P10-16:F6198  | 8     | 50 | \$155.20 |
| E0195FK20-39SN:F5442  | 97    | 20 | \$114.61 |
| HL855VF12-14:C4293    | 39    | 20 | \$130.43 |
| NAS1801-3-62:80205    | 118   | 50 | \$3.86   |
| NSA5191-3V47:F6198    | 88    | 50 | \$14.35  |
| ABS0517-20P:FAPE3     | 3     | 50 | \$60.95  |
| ABS0743U3-56:FAPE3    | 10    | 50 | \$422.31 |
| ABS0901R080-50:FAPE3  | 250   | 50 | \$2.45   |
| NAS1132E9:80205       | 740   | 50 | \$1.80   |
| NSA5516CA52NJ:F6198   | 90    | 50 | \$1.60   |
| NSA840008M150:F6198   | 16    | 50 | \$81.44  |
| SL606-3A:97393        | 11    | 50 | \$9.10   |
| ASNA2001V4D7:F6198    | 162   | 50 | \$15.24  |
| E0219ASUXV:F5442      | 1     | 20 | \$30.00  |
| E0455-03-18N:F5442    | 21    | 20 | \$32.84  |
| EN6115K10Y50:I9005    | 79    | 50 | \$43.41  |
| EN6115K5-28:I9005     | 35    | 50 | \$9.66   |
| EN6115T4X14:I9005     | 2982  | 30 | \$26.29  |
| F0N2-1212A040:H1822   | 44    | 50 | \$1.53   |
| HL19PB6-6:92215       | 72    | 50 | \$1.39   |
| HL855VF8-7:92215      | 606   | 50 | \$11.43  |
| HLT856PB8-6:F0188     | 120   | 50 | \$6.23   |
| MS20500-428:96906     | 345   | 50 | \$2.09   |
| MS21906D6:96906       | 27    | 20 | \$23.27  |
| NAS1097KE5-5-5:80205  | 98545 | 30 | \$0.03   |
| NAS513-6:80205        | 93    | 50 | \$2.02   |
| NAS517-3-9:80205      | 596   | 50 | \$0.17   |
| NSA5479BV4-4X:F6198   | 181   | 50 | \$86.25  |
| NSA931701-03:F6198    | 3     | 50 | \$499.96 |
| ASNA0096-10-31:F6198  | 93    | 50 | \$208.56 |
| DAN8-10-11X:D8518     | 1     | 30 | \$90.54  |
| EN6115V3A24:I9005     | 4     | 20 | \$80.27  |
| MS24693C58:96906      | 9800  | 20 | \$1.48   |
| NAS1515M6:80205       | 1900  | 20 | \$0.48   |
| NSA5487V7R27N:F6198   | 163   | 50 | \$110.27 |
| NSA8206-153:F6198     | 502   | 50 | \$3.58   |
| ABS0513-24:FAPE3      | 60    | 50 | \$16.77  |
| ABS0655E1B1:FAPE3     | 10    | 50 | \$5.35   |
| ABS1052C170110D:FAPE3 | 69    | 50 | \$14.16  |
| ASNA0082-204Y:F6198   | 6506  | 20 | \$1.05   |
| EN3646RS62461BY:I9005 | 19    | 50 | \$57.91  |
| MS21904W5:96906       | 50    | 30 | \$30.29  |
| NAS1102E3-17:80205    | 16177 | 50 | \$1.97   |
| NAS1149D1016J:80205   | 21748 | 50 | \$0.22   |
| NAS1149GN516P:80205   | 988   | 50 | \$0.48   |
| NSA5368-816A:F6198    | 59    | 50 | \$2.58   |
| NSA5478VHK5-18:F6198  | 214   | 50 | \$93.85  |

|                       |       |    |            |
|-----------------------|-------|----|------------|
| NSA8148-06-08:F6198   | 13    | 50 | \$17.62    |
| ABS0583-17AP:FAPE3    | 16    | 50 | \$77.85    |
| ABS0853-6-040:FAPE3   | 17    | 50 | \$1,087.39 |
| ABS0929-004-01N:FAPE3 | 97    | 50 | \$206.64   |
| E0090-16-240NN:F5442  | 239   | 20 | \$1.73     |
| MBF2113S7-350:92215   | 60    | 20 | \$74.73    |
| MS20426AD6-11:96906   | 10300 | 50 | \$0.12     |
| MS24665-362:96906     | 3134  | 50 | \$0.18     |
| MS51959-12:96906      | 3099  | 50 | \$0.27     |
| NAS1242D6-7:80205     | 152   | 20 | \$0.33     |
| NAS1399D6-5:80205     | 370   | 50 | \$1.03     |
| NAS1802-08-19:80205   | 380   | 20 | \$1.99     |
| NAS552-4D:80205       | 6     | 30 | \$47.05    |
| NAS6605D29:80205      | 470   | 20 | \$1.58     |
| NSA855116-4D:F6198    | 61    | 20 | \$31.39    |
| ASNA2065-3-080:F6198  | 61    | 50 | \$16.22    |
| D155-0550:06090       | 301   | 50 | \$10.30    |
| E0089-06-100:F5442    | 722   | 30 | \$1.33     |
| E0089-08-125N:F5442   | 320   | 50 | \$2.16     |
| EN6115-6Y20:I9005     | 44    | 20 | \$49.51    |
| EN6115T3A12:I9005     | 955   | 50 | \$5.58     |
| MS21209C0415:96906    | 300   | 50 | \$0.65     |
| MS21907K6:96906       | 5     | 20 | \$79.26    |
| MS21908-10:96906      | 14    | 50 | \$90.11    |
| MS21919WDF16:96906    | 720   | 20 | \$4.07     |
| MS9915-13:96906       | 66    | 20 | \$3.35     |
| NAS1068A06:80205      | 1140  | 50 | \$0.57     |
| NAS1132E5P:80205      | 1175  | 20 | \$0.69     |
| NAS501-3-7:80205      | 210   | 50 | \$36.59    |
| NAS560HK3-4:80205     | 400   | 20 | \$0.69     |
| DAN8-8-3Y:D8518       | 3828  | 50 | \$3.52     |
| E0163D01-16X:F5442    | 99    | 20 | \$211.77   |
| E0415C3LM009E:F5442   | 2     | 50 | \$669.69   |
| EN6115T6-24:I9005     | 191   | 30 | \$6.26     |
| K8000-3:K6405         | 20    | 50 | \$5.27     |
| NAS1149D2116J:80205   | 813   | 50 | \$0.50     |
| NAS1669-3L6:80205     | 101   | 30 | \$5.11     |
| NAS6704U34:80205      | 782   | 50 | \$6.72     |
| NSA5103-3:F6198       | 172   | 50 | \$4.24     |
| NSA55161-114:F6198    | 2     | 50 | \$20.70    |
| NSA8206-013:F6198     | 294   | 50 | \$9.82     |
| SL61WT750P:99167      | 37    | 50 | \$142.91   |
| ASNA2027V4-16:F6198   | 7     | 50 | \$15.91    |
| EN3645M0DN05BN:I9005  | 20    | 20 | \$18.76    |
| EN6114V6Y27:I9005     | 89    | 20 | \$362.26   |
| MS24694C8:96906       | 9452  | 50 | \$0.17     |
| NAS1097U4-3:80205     | 236   | 20 | \$7.98     |
| NSA8551-2-140:F6198   | 496   | 50 | \$17.64    |
| NSA855121-23:F6198    | 1     | 50 | \$2,195.06 |
| ABS1362-10-16B:FAPE3  | 42    | 50 | \$55.55    |



|                       |      |    |            |
|-----------------------|------|----|------------|
| HL12VF5-10:92215      | 312  | 50 | \$3.64     |
| MS20470AD7-14:96906   | 101  | 50 | \$19.15    |
| MS51957-17:96906      | 375  | 50 | \$0.14     |
| NAS43DD3-14FC:80205   | 3742 | 20 | \$1.22     |
| NAS6203-20:80205      | 387  | 50 | \$0.74     |
| NAS6203-5X:80205      | 284  | 50 | \$18.26    |
| NSA5399-6A32A:F6198   | 200  | 50 | \$139.44   |
| AN814-12DL:88044      | 8    | 50 | \$25.18    |
| BHW1726C7P:27238      | 20   | 20 | \$20.23    |
| EN6115T5X22:I9005     | 49   | 50 | \$65.11    |
| MS21056-5:96906       | 10   | 20 | \$7.41     |
| MS24665-163:96906     | 1755 | 20 | \$0.17     |
| NAS1352-06H26P:80205  | 89   | 50 | \$17.25    |
| NSA5399-5-14:F6198    | 200  | 50 | \$54.12    |
| 21215DC3212J:F0111    | 3068 | 50 | \$0.43     |
| AN525-832R10:88044    | 2317 | 50 | \$0.09     |
| ASNA2314-3-9:F6198    | 83   | 20 | \$121.94   |
| EN6114K7Y32:I9005     | 6    | 20 | \$339.58   |
| HL19PB5-2:92215       | 220  | 20 | \$1.56     |
| NAS42DD6-80FC:80205   | 45   | 20 | \$1.13     |
| NSA5398-10-56A:F6198  | 85   | 50 | \$88.94    |
| NSA5478BV5-5:F6198    | 950  | 50 | \$2.61     |
| NSA5478BV5-6:F6198    | 994  | 50 | \$63.42    |
| SP112N:K7766          | 244  | 50 | \$3.07     |
| ABS0898AA331:FAPE3    | 6    | 50 | \$201.24   |
| AS21919WDG12:81343    | 55   | 20 | \$5.58     |
| ASNA2054C4-08:F6198   | 7    | 30 | \$9.02     |
| E0247C0S:F5442        | 995  | 50 | \$7.10     |
| EN2997SE02255B8:I9005 | 20   | 50 | \$81.30    |
| EN4265AN12ER:I9005    | 45   | 20 | \$105.36   |
| NAS1801-3-37:80205    | 750  | 50 | \$0.55     |
| NAS1834A3-500:80205   | 60   | 50 | \$5.44     |
| NAS6704U96:80205      | 492  | 50 | \$23.30    |
| NSA5353-04A:F6198     | 3350 | 50 | \$0.24     |
| ABS0113-10-24X:FAPE3  | 27   | 50 | \$164.45   |
| AS8623D:U1653         | 533  | 50 | \$35.73    |
| ASNA0093-10-32:F6198  | 11   | 50 | \$59.85    |
| E0092-41-220:F5442    | 240  | 50 | \$3.86     |
| HLT901BV6-9:73197     | 285  | 50 | \$10.04    |
| MS24665-446:96906     | 769  | 20 | \$0.41     |
| MS27111-2:96906       | 2223 | 50 | \$0.64     |
| NAS1103-3:80205       | 4200 | 20 | \$0.17     |
| NAS1149D1490J:80205   | 2499 | 30 | \$0.47     |
| NAS1423C7LH:80205     | 19   | 50 | \$8.03     |
| NSA5399-9-20:F6198    | 97   | 20 | \$69.12    |
| NSA9117-61F:F6198     | 49   | 50 | \$22.41    |
| ABS0783B06C:FAPE3     | 84   | 50 | \$12.56    |
| ABS1433D0HR065:FAPE3  | 1    | 50 | \$1,464.14 |
| E0163D18-01:F5442     | 22   | 50 | \$345.83   |
| MS9555-04:96906       | 231  | 50 | \$3.33     |



|                       |        |    |          |
|-----------------------|--------|----|----------|
| NAS1611-021A:80205    | 75     | 50 | \$0.65   |
| NAS5900-6:80205       | 506    | 50 | \$3.46   |
| ABS0114V5-4:FAPE3     | 25     | 50 | \$3.31   |
| ABS0255-5-550Z:FAPE3  | 176    | 50 | \$5.75   |
| AN565BC6H4:88044      | 39     | 50 | \$3.29   |
| ASNA2001T4-11Y:F6198  | 18     | 30 | \$63.05  |
| MS20392-13C15:96906   | 120    | 50 | \$7.70   |
| MS21909W5:96906       | 3      | 30 | \$20.85  |
| NAS1580C3R12:80205    | 324    | 50 | \$0.88   |
| NAS561F3-8:80205      | 555    | 50 | \$0.35   |
| NSA932805-03B:F6198   | 26     | 50 | \$754.66 |
| ABS0396C06FA:FAPE3    | 22     | 50 | \$7.87   |
| ABS1028D00EA335:FAPE3 | 11     | 50 | \$862.50 |
| EN6101D3-05-5:I9005   | 116531 | 50 | \$0.03   |
| EN6114K9Y15:I9005     | 42     | 50 | \$124.41 |
| EN6115K3X16:I9005     | 94     | 50 | \$19.01  |
| EN6115K9Y12:I9005     | 1      | 50 | \$604.07 |
| MS21209F6-20P:96906   | 29     | 20 | \$6.23   |
| NAS603-15:80205       | 2851   | 50 | \$0.22   |
| NSA5359-4-14:F6198    | 22     | 50 | \$177.67 |
| EN3646A61419BY:I9005  | 2      | 50 | \$15.73  |
| EN6069T5-06:I9005     | 234    | 50 | \$1.53   |
| NAS1101E06-16:80205   | 263    | 20 | \$0.76   |
| NAS6307U13:80205      | 230    | 20 | \$15.91  |
| NAS6612D22:80205      | 190    | 20 | \$90.23  |
| NSA5356-10-28:F6198   | 14     | 20 | \$101.07 |
| NSA5479BV5-10:F6198   | 249    | 50 | \$167.53 |
| ABS0783B04C:FAPE3     | 186    | 50 | \$12.56  |
| ABS1835AAA05A01:FAPE3 | 4      | 50 | \$147.46 |
| EN6115-5Y18:I9005     | 92     | 50 | \$47.79  |
| EN6115K3X22:I9005     | 115    | 30 | \$33.53  |
| HL412VF6-11:92215     | 76     | 50 | \$8.84   |
| HLT951PN14-19:73197   | 98     | 50 | \$47.88  |
| MS21076L06N:96906     | 1356   | 50 | \$2.49   |
| NAS1305-15:80205      | 240    | 20 | \$3.21   |
| NAS1790C3R2P:80205    | 1881   | 50 | \$0.79   |
| NAS6404U8:80205       | 150    | 50 | \$5.88   |
| NAS6614D31:80205      | 16     | 20 | \$46.42  |
| NAS6705DU34:80205     | 145    | 50 | \$8.60   |
| NSA5042-05-290:F6198  | 1006   | 50 | \$79.73  |
| NSA5357-6-16:F6198    | 67     | 50 | \$323.19 |
| NSA5516CA35NJ:F6198   | 471    | 20 | \$1.29   |
| NSA936507TG3002:F6198 | 20     | 50 | \$40.66  |
| V40G23-10BP:D0680     | 94     | 50 | \$8.60   |
| ABS0142-6:FAPE3       | 321    | 50 | \$2.16   |
| ABS1547-003E02N:FAPE3 | 1      | 50 | \$243.53 |
| CR2248-4-3:11815      | 1313   | 30 | \$0.88   |
| EN6101D4-13:I9005     | 5      | 20 | \$9.13   |
| MS90354-0607:96906    | 189    | 50 | \$2.29   |
| NAS1672-08L3:80205    | 68     | 20 | \$8.17   |



|                       |        |    |          |
|-----------------------|--------|----|----------|
| NAS1832C4-7:80205     | 124    | 50 | \$4.70   |
| NAS6704U52:80205      | 95     | 50 | \$102.29 |
| NAS6706U6:80205       | 470    | 50 | \$11.83  |
| NSA5479BV5-6:F6198    | 1296   | 50 | \$10.23  |
| NSA855113-36W:F6198   | 52     | 50 | \$46.14  |
| A228L20Y:K7766        | 92     | 50 | \$56.82  |
| ABS2044A08F010:FAPE3  | 55     | 50 | \$50.07  |
| AS3582-007:81343      | 127    | 50 | \$0.33   |
| DAN7-10-3X:D8518      | 70     | 50 | \$155.80 |
| DHS1906DD:U1598       | 69     | 50 | \$9.82   |
| MS20470D6-13:96906    | 300    | 20 | \$0.19   |
| NAS1132E4P:80205      | 144    | 50 | \$0.91   |
| NAS6603-52:80205      | 256    | 20 | \$3.11   |
| NSA5476VHK5-6:F6198   | 375    | 20 | \$11.17  |
| NSA55137-117:F6198    | 136    | 50 | \$3.84   |
| ABS0114V4D9:FAPE3     | 244    | 50 | \$1.42   |
| HLT900BV10-12:73197   | 405    | 50 | \$35.69  |
| HLT901BV8-15:73197    | 16     | 50 | \$61.59  |
| MS20002-16:96906      | 1709   | 30 | \$0.47   |
| MS20427M6-9:96906     | 100    | 20 | \$23.42  |
| MS21254-5LL:96906     | 10     | 50 | \$37.51  |
| MS35650-3312:96906    | 160    | 50 | \$1.31   |
| MS51862-4:96906       | 4421   | 50 | \$0.07   |
| NAS1195C4XM:80205     | 420    | 30 | \$0.68   |
| NAS1611-250A:80205    | 140    | 30 | \$6.27   |
| NAS42DD6-19FC:80205   | 1880   | 20 | \$0.38   |
| NAS6204-21D:80205     | 182    | 20 | \$1.32   |
| NAS623-2-6:80205      | 1050   | 50 | \$0.45   |
| NSA5042-06-263:F6198  | 100    | 50 | \$4.98   |
| NSA5414-48-22:F6198   | 470    | 20 | \$6.38   |
| AS3209-006:81343      | 10000  | 50 | \$0.42   |
| ASNA0033-180:F6198    | 96     | 50 | \$6.93   |
| DIN65399-2409BF:D8286 | 179492 | 50 | \$0.02   |
| EN6114-12-36:I9005    | 9      | 50 | \$352.16 |
| EN6114K8-27:I9005     | 480    | 50 | \$12.33  |
| MS16625-3043:96906    | 437    | 50 | \$0.10   |
| MS16995-17:96906      | 1083   | 50 | \$1.83   |
| NAS1304-42:80205      | 1064   | 50 | \$0.96   |
| NSA5121CR05-070:F6198 | 27     | 50 | \$3.24   |
| ABS5642AEL29-8:FAPE3  | 100    | 50 | \$1.76   |
| ASNA0243A08060:F6198  | 9      | 50 | \$21.71  |
| EN6101D6X24:I9005     | 116    | 50 | \$110.77 |
| EN6114-14Y28:I9005    | 197    | 20 | \$57.18  |
| EN6115K8-43:I9005     | 71     | 20 | \$73.43  |
| EN6115T4X6:I9005      | 41     | 50 | \$28.71  |
| HL10VDF6-7:92215      | 45     | 20 | \$3.31   |
| MS20392-2P23:96906    | 37     | 50 | \$5.10   |
| MS20426B3-6:96906     | 9800   | 50 | \$0.02   |
| MS28773-08:96906      | 100    | 20 | \$0.57   |
| NAS1305-21:80205      | 350    | 20 | \$0.57   |

|                       |      |    |            |
|-----------------------|------|----|------------|
| NAS1351C3-16P:80205   | 80   | 50 | \$82.95    |
| NAS1801-4D11:80205    | 428  | 50 | \$2.85     |
| NAS6603-8X:80205      | 243  | 20 | \$27.28    |
| NAS697A4:80205        | 840  | 50 | \$0.58     |
| NSA5378-5A16:F6198    | 430  | 50 | \$14.67    |
| NSA5398-6A24A:F6198   | 100  | 50 | \$108.54   |
| NSA5398-9-20A:F6198   | 124  | 50 | \$136.46   |
| NSA5476BV7-21:F6198   | 542  | 50 | \$25.91    |
| NSA5713R4011:F6198    | 5276 | 50 | \$0.21     |
| PLT110-5-6:98524      | 140  | 50 | \$5.29     |
| ABS0114V6-11:FAPE3    | 528  | 50 | \$7.06     |
| ASNA0093-7-17:F6198   | 96   | 20 | \$61.88    |
| D10023-060406:14798   | 5    | 20 | \$288.05   |
| NAS1104-13:80205      | 435  | 30 | \$0.96     |
| NSA5031-5-17:F6198    | 90   | 50 | \$6.88     |
| ABS0201-01B9:FAPE3    | 125  | 50 | \$16.16    |
| ABS0785B07C:FAPE3     | 66   | 50 | \$7.41     |
| E0467A03:F5442        | 11   | 50 | \$70.54    |
| EN6115-12X28:I9005    | 97   | 50 | \$183.65   |
| HLT902BV12-25:92215   | 17   | 50 | \$25.95    |
| MS9566-21:96906       | 32   | 50 | \$4.43     |
| NAS1149D0516H:80205   | 2475 | 50 | \$0.07     |
| NAS1611-033A:80205    | 1848 | 20 | \$1.03     |
| NAS6604-54:80205      | 185  | 20 | \$22.70    |
| NSA5479BV5-17Y:F6198  | 4    | 50 | \$61.69    |
| NSA5487V8R31N:F6198   | 15   | 50 | \$158.94   |
| E0073-22-41T:F5442    | 10   | 50 | \$108.05   |
| E0261CF20U:F5442      | 5    | 20 | \$27.90    |
| MS20426D6-9:96906     | 3732 | 20 | \$0.17     |
| MS20427-8X8:96906     | 4275 | 50 | \$0.39     |
| MS28782-3:96906       | 230  | 50 | \$1.22     |
| NAS1833C3-433:80205   | 599  | 50 | \$2.85     |
| NAS620A4L:80205       | 588  | 50 | \$0.14     |
| NSA5477BV5-20:F6198   | 416  | 20 | \$60.94    |
| NSA5653-21-0275:F6198 | 100  | 50 | \$17.52    |
| ABS1381-19F1216:FAPE3 | 82   | 50 | \$25.40    |
| AS3209-131:81343      | 80   | 50 | \$0.99     |
| EN6075-014:I9005      | 92   | 20 | \$4.08     |
| EN6114K10X8:I9005     | 6    | 50 | \$26.74    |
| NAS1057T6-021:80205   | 202  | 50 | \$2.51     |
| NAS1101E3-4:80205     | 334  | 20 | \$1.90     |
| NAS1200-5-8:80205     | 29   | 50 | \$18.40    |
| NSA855113-15D:F6198   | 83   | 50 | \$36.02    |
| ABS0638C24:FAPE3      | 28   | 50 | \$2.21     |
| ABS0946V04L:FAPE3     | 3    | 50 | \$264.49   |
| ABS1400S00EK674:FAPE3 | 30   | 50 | \$1,174.47 |
| DAN426-01-3-7:D8518   | 100  | 50 | \$4.41     |
| EN6115K3A22:I9005     | 71   | 20 | \$79.16    |
| EN6115T9X25:I9005     | 95   | 50 | \$97.98    |
| HLT912BV6-7:92215     | 1785 | 50 | \$14.84    |



|                       |      |    |          |
|-----------------------|------|----|----------|
| HST10BJ8-6:73197      | 10   | 50 | \$6.66   |
| M8791-1-110:81349     | 799  | 30 | \$0.60   |
| MS21209F4-30P:96906   | 63   | 50 | \$5.45   |
| MS9386-009:96906      | 1303 | 50 | \$0.17   |
| NAS1291C8:80205       | 79   | 20 | \$3.21   |
| NAS1304-10D:80205     | 277  | 50 | \$0.94   |
| NAS1368N16B:80205     | 1200 | 20 | \$0.84   |
| NAS6704U10X:80205     | 3    | 20 | \$135.87 |
| NSA5154V8-25:F6198    | 79   | 50 | \$100.42 |
| NSA5372E816C:F6198    | 18   | 50 | \$1.98   |
| NSA5477BV7-23:F6198   | 27   | 50 | \$50.83  |
| NSA5487V6R19N:F6198   | 176  | 50 | \$101.02 |
| ABS0108T075:FAPE3     | 4    | 50 | \$82.18  |
| AN315D7R:88044        | 24   | 50 | \$3.14   |
| DAN16-10-18:D8518     | 12   | 20 | \$17.86  |
| MS21141-0504:96906    | 20   | 50 | \$2.47   |
| NAS1398M4-2:80205     | 200  | 50 | \$3.15   |
| NAS1726C7S:80205      | 96   | 50 | \$33.02  |
| NAS1791C4-1NP:80205   | 52   | 30 | \$2.78   |
| NAS603-3P:80205       | 1668 | 50 | \$0.31   |
| NAS6705D17:80205      | 86   | 30 | \$11.39  |
| NAS6705DU46:80205     | 132  | 50 | \$14.43  |
| NAS6707U34:80205      | 80   | 50 | \$9.64   |
| NSA5042C10-510:F6198  | 105  | 50 | \$53.88  |
| NSA5372PD816B:F6198   | 6767 | 50 | \$0.21   |
| NSA5478BV5-19:F6198   | 3    | 50 | \$37.24  |
| NSA5479BV8-22:F6198   | 12   | 50 | \$58.50  |
| EN2997SE02430FN:I9005 | 1    | 20 | \$317.25 |
| MS21047L6:96906       | 516  | 20 | \$1.44   |
| NAS1398D5-6:80205     | 715  | 50 | \$1.24   |
| NAS6703HA17:80205     | 7    | 20 | \$130.69 |
| NSA5089-4-12:F6198    | 1100 | 50 | \$7.09   |
| NSA55161-005:F6198    | 217  | 50 | \$6.47   |
| AN924-24J:88044       | 28   | 20 | \$25.11  |
| AS41089C:81343        | 91   | 50 | \$2.40   |
| ASNA2328-3-18:F6198   | 1060 | 50 | \$8.67   |
| EN3646A61808AN:I9005  | 165  | 20 | \$32.34  |
| EN6115-7-14:I9005     | 42   | 20 | \$596.76 |
| EN6115V6Y24:I9005     | 44   | 50 | \$69.64  |
| HL741VF6-5:92215      | 360  | 20 | \$10.45  |
| M25988-4-020:81349    | 50   | 50 | \$1.68   |
| MS24673-3:96906       | 620  | 20 | \$1.68   |
| MS9490-08:96906       | 265  | 50 | \$4.91   |
| NSA937901CA13:F6198   | 5    | 50 | \$96.10  |
| ABS0114V4-20:FAPE3    | 5215 | 50 | \$4.09   |
| CR7770S05-05EE:11815  | 67   | 50 | \$11.45  |
| EN2997SE61203A6:I9005 | 50   | 20 | \$52.51  |
| EN6114K5Y24:I9005     | 33   | 50 | \$12.01  |
| EN6114K8X40:I9005     | 196  | 50 | \$165.18 |
| EN6114K8Y26:I9005     | 42   | 20 | \$70.00  |

|                       |       |    |            |
|-----------------------|-------|----|------------|
| NSA5020-3-1:F6198     | 36    | 50 | \$3.60     |
| NSA5479VHK7-18:F6198  | 670   | 20 | \$14.02    |
| ABS0114T4-10X:FAPE3   | 53    | 50 | \$24.73    |
| ABS0648-1E14:FAPE3    | 3     | 50 | \$131.55   |
| ASNA3752-161612:F6198 | 8     | 20 | \$317.89   |
| CR2248-4-2:11815      | 1283  | 50 | \$1.21     |
| EN6114L4-4:I9005      | 972   | 50 | \$8.92     |
| HL741VF6-3:92215      | 510   | 50 | \$2.51     |
| NAS1103-12:80205      | 662   | 20 | \$0.81     |
| NSA5031-4D34:F6198    | 213   | 50 | \$27.90    |
| NSA5356-8-19:F6198    | 200   | 50 | \$70.13    |
| NSA5479BV5-9:F6198    | 1333  | 50 | \$2.92     |
| ABS1070D08-036:FAPE3  | 95    | 50 | \$8.99     |
| EN6114-12Y34:I9005    | 89    | 30 | \$140.68   |
| EN6114-18Y29:I9005    | 9     | 20 | \$2,495.99 |
| MS20426D3-8:96906     | 1696  | 50 | \$0.07     |
| MS20426DD7-15:96906   | 90    | 20 | \$12.84    |
| MS20470A6-8:96906     | 2700  | 50 | \$0.09     |
| MS21250-16070:96906   | 8     | 20 | \$72.57    |
| MS21914-8K:96906      | 228   | 20 | \$24.38    |
| NAS1149D2190K:80205   | 629   | 50 | \$1.35     |
| NAS6707D26:80205      | 17    | 50 | \$186.39   |
| NSA5487V6R22N:F6198   | 181   | 50 | \$101.71   |
| NSA855140-27D:F6198   | 50    | 50 | \$126.87   |
| ABS1533C3LE6:FAPE3    | 228   | 50 | \$18.53    |
| AN924-16J:88044       | 82    | 50 | \$69.36    |
| EN3660-004K16A:I9005  | 36    | 50 | \$20.28    |
| EN6115-7Y8:I9005      | 10    | 50 | \$1,320.67 |
| HL413VF8-18:C4293     | 390   | 20 | \$10.35    |
| HLT856PN6-5:92215     | 1000  | 50 | \$6.16     |
| MS14104-10:96906      | 6     | 50 | \$37.18    |
| MS20470AD2-3:96906    | 10000 | 30 | \$0.02     |
| MS20470D7-9:96906     | 1300  | 20 | \$0.09     |
| MS29513-248:96906     | 225   | 50 | \$1.30     |
| MS9211-24:96906       | 88    | 50 | \$29.44    |
| NAS1132E8:80205       | 250   | 20 | \$1.32     |
| NAS603-22P:80205      | 1025  | 50 | \$0.22     |
| NAS6203-10:80205      | 2970  | 50 | \$0.47     |
| NSA5359-3-14:F6198    | 16    | 50 | \$8.51     |
| NSA5477BV5-16:F6198   | 368   | 50 | \$43.05    |
| AE2139BAATA520:00624  | 10    | 50 | \$1,408.60 |
| AS4370J08L:U1653      | 952   | 50 | \$11.94    |
| ASNA2886C03C:F6198    | 146   | 20 | \$58.16    |
| CR3553P6-05:11815     | 80    | 20 | \$5.05     |
| MS21916J4-2:96906     | 6     | 50 | \$24.99    |
| MS25281R22:96906      | 81    | 20 | \$5.51     |
| NAS6304U34:80205      | 40    | 20 | \$4.39     |
| NAS6605-26:80205      | 340   | 20 | \$3.36     |
| NAS6704DU24:80205     | 960   | 30 | \$5.42     |
| NSA5398-4-14A:F6198   | 9     | 50 | \$82.56    |



|                       |       |    |             |
|-----------------------|-------|----|-------------|
| ABS0907K4-6Y:FAPE3    | 109   | 50 | \$45.56     |
| ABS1028R00CF371:FAPE3 | 8     | 50 | \$1,174.26  |
| ASNA2041-4-13H:F6198  | 469   | 50 | \$14.50     |
| DAN7-12-13X:D8518     | 54    | 50 | \$528.43    |
| HA1083-1:83014        | 3     | 50 | \$13,332.75 |
| NAS1097AD8-24:80205   | 4188  | 50 | \$1.49      |
| NAS1399D6-2:80205     | 480   | 50 | \$1.63      |
| NSA5120-8-045:F6198   | 50    | 50 | \$18.07     |
| NSA5479BV4-7Y:F6198   | 14    | 20 | \$39.30     |
| 236482:B1255          | 274   | 50 | \$43.16     |
| 8660-140:F0225        | 20    | 50 | \$7.44      |
| ASNA2027V5-18:F6198   | 8     | 50 | \$16.11     |
| EN6101KE5-06:I9005    | 477   | 30 | \$2.67      |
| MS16562-65:96906      | 400   | 50 | \$0.31      |
| MS16998-50:96906      | 149   | 50 | \$1.94      |
| MS24693BB52:96906     | 9502  | 50 | \$0.19      |
| NAS6706-25:80205      | 10    | 20 | \$49.92     |
| NAS6707U11:80205      | 12    | 50 | \$23.84     |
| ABS0898AN195:FAPE3    | 4     | 50 | \$184.17    |
| EN2997KE516:I9005     | 1     | 50 | \$53.23     |
| HST756JB6-16:73197    | 491   | 50 | \$7.88      |
| MS90354U0605:96906    | 169   | 50 | \$1.38      |
| NAS1241AD4-15:80205   | 150   | 20 | \$0.94      |
| NAS1670-3L7:80205     | 50    | 50 | \$10.86     |
| NAS6204-9D:80205      | 65    | 50 | \$1.08      |
| NAS623-5-15:80205     | 665   | 20 | \$1.01      |
| NAS6707-7:80205       | 50    | 20 | \$39.86     |
| NSA5357-5-24:F6198    | 3     | 20 | \$94.72     |
| NSA55131-104:F6198    | 271   | 50 | \$6.44      |
| SP123D:K5640          | 11930 | 50 | \$0.39      |
| 66332-12A:F1983       | 2     | 50 | \$49.59     |
| ABS0388A37A:FAPE3     | 494   | 50 | \$4.27      |
| ASNA0123-9-10:F6198   | 10    | 50 | \$1,646.86  |
| ASNA2857-130:F6198    | 40    | 50 | \$72.60     |
| E0091-40-260NN:F5442  | 167   | 20 | \$6.50      |
| LN9025-0810L:D8442    | 3673  | 50 | \$1.33      |
| NAS1149C0532B:80205   | 22840 | 50 | \$0.06      |
| NAS6205-7:80205       | 242   | 50 | \$1.23      |
| NAS6704HU4:80205      | 411   | 50 | \$5.15      |
| NSA5399-6-18:F6198    | 182   | 50 | \$61.60     |
| NSA5477BV7-18:F6198   | 400   | 50 | \$14.12     |
| NSA5479BV5-24:F6198   | 399   | 20 | \$20.94     |
| EN2997RS60803B9:I9005 | 22    | 20 | \$32.33     |
| EN6101D7-08:I9005     | 15461 | 20 | \$0.09      |
| LH12105T12:72962      | 8     | 50 | \$197.85    |
| MS90354S0506:96906    | 137   | 50 | \$1.78      |
| NAS1100-4-10B:80205   | 520   | 20 | \$0.41      |
| NAS1200M6-7:80205     | 616   | 30 | \$0.60      |
| NAS1669-08L9:80205    | 50    | 20 | \$13.61     |
| NAS6307U15:80205      | 247   | 50 | \$16.30     |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| NAS77-4-038:80205     | 40    | 20 | \$24.35  |
| NSA5121-03-300:F6198  | 6     | 50 | \$77.27  |
| NSA5154VA8-13:F6198   | 49    | 50 | \$296.22 |
| NSA5482PN10-22:F6198  | 87    | 50 | \$136.47 |
| NSA5609-11-72:F6198   | 28    | 30 | \$59.11  |
| ABS0787D116C:FAPE3    | 1201  | 50 | \$9.66   |
| C10GT3-20:83930       | 100   | 50 | \$69.46  |
| EN6081KE5-09:I9005    | 15975 | 50 | \$0.21   |
| EN6115V5Y7:I9005      | 83    | 30 | \$25.84  |
| NAS1304-26:80205      | 5923  | 20 | \$0.81   |
| NAS463XDD10L:80205    | 17168 | 50 | \$0.17   |
| NAS9302E5-04:80205    | 134   | 50 | \$1.41   |
| NSA937901RB0170:F6198 | 51    | 50 | \$9.75   |
| ABS1387T100808:FAPE3  | 10    | 50 | \$275.65 |
| ABS1870F20K04NB:FAPE3 | 34    | 50 | \$392.33 |
| AS27852:U1653         | 135   | 50 | \$10.62  |
| AS62221:U1653         | 100   | 50 | \$11.86  |
| E0161D01A02X:F5442    | 99    | 50 | \$181.12 |
| EN3646RS61006MN:I9005 | 3     | 20 | \$42.22  |
| HL856VF6-11:73197     | 37    | 50 | \$44.94  |
| NSA54213-405DCA:F6198 | 38    | 50 | \$2.15   |
| NSA5476BV5-13:F6198   | 999   | 50 | \$52.99  |
| NSA5479BV4-13:F6198   | 1315  | 50 | \$7.15   |
| NSA55131-118:F6198    | 84    | 20 | \$1.20   |
| T411-1010-01:F0219    | 10    | 50 | \$438.50 |
| ABS0113-10-26X:FAPE3  | 3     | 50 | \$164.45 |
| ABS0114V3H17:FAPE3    | 85    | 50 | \$4.79   |
| ASNA2041-2-04H:F6198  | 290   | 50 | \$1.95   |
| HL413VF6-22:C4293     | 70    | 50 | \$233.24 |
| HLT924BJ6-10:73197    | 65    | 20 | \$27.18  |
| MS17987C726:96906     | 12    | 50 | \$464.85 |
| NAS6205-23D:80205     | 500   | 20 | \$1.46   |
| NSA8147-16-08:F6198   | 3     | 20 | \$27.52  |
| NSA937901RB0180:F6198 | 32    | 50 | \$12.89  |
| ABS0477D1010:FAPE3    | 2     | 50 | \$144.33 |
| CCR264CS4-10PR:11815  | 1054  | 50 | \$1.15   |
| DAN6-16-22X:D8518     | 100   | 50 | \$39.66  |
| DAN7-12-11X:D8518     | 19    | 50 | \$114.85 |
| DIN933M5X10:D8286     | 850   | 20 | \$0.21   |
| HLT637AP12-19:73197   | 21    | 50 | \$459.70 |
| M25988-1-016:81349    | 585   | 30 | \$0.48   |
| M83413-8G12BB:81349   | 23    | 20 | \$84.46  |
| NAS6608D60:80205      | 39    | 20 | \$19.46  |
| NAS6703-29:80205      | 9     | 20 | \$7.98   |
| NAS6706D32:80205      | 59    | 50 | \$22.86  |
| NAS7803U2:80205       | 690   | 50 | \$1.51   |
| NSA5516A07ND:F6198    | 1000  | 20 | \$0.63   |
| NSA5516A12ND:F6198    | 520   | 50 | \$1.17   |
| ABS5098ACF29-1:FAPE3  | 60    | 50 | \$5.77   |
| AN929-12J:88044       | 4     | 20 | \$17.71  |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| ASNA0009A110:F6198    | 426   | 50 | \$5.46   |
| EN6115-6Y15:I9005     | 100   | 50 | \$153.08 |
| EN6115K4-24:I9005     | 240   | 50 | \$16.03  |
| MS9209-07:96906       | 356   | 50 | \$8.80   |
| NAS602-13P:80205      | 11327 | 20 | \$0.17   |
| NSA5372-816DX:F6198   | 95    | 50 | \$8.24   |
| NSA5477BV10-26:F6198  | 16    | 20 | \$298.98 |
| NSA5486V6R18N:F6198   | 6     | 50 | \$46.28  |
| NSA937901E02:F6198    | 273   | 20 | \$144.73 |
| ABS0113-10-21X:FAPE3  | 4     | 50 | \$74.27  |
| ABS0114V4D49:FAPE3    | 912   | 50 | \$18.86  |
| ASNA2053-06A:F6198    | 417   | 50 | \$4.97   |
| EN3545E09FXA12A:I9005 | 5     | 20 | \$119.36 |
| MS14145-3:96906       | 200   | 50 | \$2.99   |
| MS21075-06N:96906     | 1040  | 50 | \$1.10   |
| MS90451-7132:96906    | 241   | 20 | \$1.99   |
| NAS1080D05:80205      | 29298 | 50 | \$0.12   |
| NAS1242AD4-12:80205   | 69    | 50 | \$1.18   |
| NAS1739C4-5:80205     | 103   | 50 | \$4.24   |
| NSA5089-6D14:F6198    | 115   | 50 | \$11.27  |
| NSA5089V4-4:F6198     | 570   | 50 | \$1.98   |
| ASNA2352T4-7:F6198    | 484   | 50 | \$4.51   |
| D33KBA402:D1285       | 5     | 50 | \$134.67 |
| DAN7-10-9Y:D8518      | 7     | 50 | \$58.21  |
| EN2997SE61412AN:I9005 | 17    | 20 | \$41.90  |
| EN6115-10X36:I9005    | 18    | 20 | \$257.79 |
| MS20470DD6-13:96906   | 60    | 50 | \$0.81   |
| MS21047L4:96906       | 1582  | 50 | \$1.35   |
| NAS1714C2-4TW:80205   | 31    | 20 | \$9.58   |
| NAS6606D14:80205      | 190   | 50 | \$7.36   |
| NSA938361A13A:F6198   | 39    | 20 | \$55.55  |
| SL61WT562P:99167      | 1     | 50 | \$103.78 |
| DAN7-10-5:D8518       | 1003  | 50 | \$7.98   |
| EN3660-005K12A:I9005  | 98    | 50 | \$31.17  |
| EN6114K9X28:I9005     | 34    | 50 | \$124.41 |
| HLT912BV8-16:92215    | 1185  | 50 | \$22.69  |
| MS35207-285:96906     | 3100  | 50 | \$0.26   |
| MS9565-12:96906       | 241   | 50 | \$2.18   |
| NAS1103-9:80205       | 1520  | 50 | \$1.11   |
| NAS1801-4-28:80205    | 648   | 50 | \$1.06   |
| NAS4404-15:80205      | 615   | 50 | \$0.46   |
| NAS6706DU14:80205     | 58    | 50 | \$7.75   |
| NAS6804U6:80205       | 100   | 50 | \$21.96  |
| NSA5516A80NJ:F6198    | 290   | 20 | \$3.12   |
| NSA855111C10:F6198    | 9     | 50 | \$29.96  |
| ABS0114T5D15:FAPE3    | 48    | 50 | \$3.73   |
| ASNA0081A203:F6198    | 30    | 20 | \$10.33  |
| CR7774S05-04:11815    | 400   | 20 | \$4.46   |
| EN6115V8-7:I9005      | 962   | 50 | \$13.18  |
| NAS1241AD4-11:80205   | 1144  | 20 | \$0.57   |

|                       |        |    |          |
|-----------------------|--------|----|----------|
| NAS600-16P:80205      | 208    | 20 | \$0.14   |
| NAS600-3P:80205       | 4947   | 50 | \$0.07   |
| NAS6706DU18:80205     | 44     | 50 | \$8.79   |
| NSA5476VHK7-16:F6198  | 24     | 20 | \$8.89   |
| NSA5479BV5-18:F6198   | 393    | 50 | \$37.08  |
| NSA933667-02-5:F6198  | 4      | 50 | \$648.30 |
| ASNA2397-10LF:F6198   | 121    | 50 | \$4.88   |
| DIN933M5X12:D8286     | 500    | 20 | \$0.38   |
| EN6114K6Y26:I9005     | 291    | 20 | \$43.28  |
| NAS1102E04-8:80205    | 451    | 50 | \$0.55   |
| NAS1149E0963R:80205   | 2620   | 50 | \$0.79   |
| ABS0696X2-2-32:FAPE3  | 14     | 50 | \$1.98   |
| EN6081KE6-09:I9005    | 4550   | 50 | \$0.51   |
| EN6114-6Y12:I9005     | 181    | 50 | \$101.12 |
| EN6115V10-12:I9005    | 56     | 30 | \$37.21  |
| HLT857PN20-22:92215   | 13     | 50 | \$117.75 |
| M25988-1-024:81349    | 100    | 50 | \$1.39   |
| MS20426A3-6:96906     | 4498   | 50 | \$0.03   |
| MS9518-06:96906       | 1063   | 50 | \$0.67   |
| NAS1100-02-7:80205    | 4625   | 50 | \$0.27   |
| NAS1101-08-7:80205    | 1536   | 50 | \$0.33   |
| NAS1401-5D3G:80205    | 450    | 50 | \$5.85   |
| NAS8602-1:80205       | 2078   | 50 | \$0.36   |
| EN6115V6X28:I9005     | 77     | 50 | \$69.64  |
| NAS1022N4:80205       | 900    | 20 | \$0.27   |
| NAS1101E3-14:80205    | 47     | 50 | \$11.75  |
| NAS1329A3K80:80205    | 1334   | 50 | \$0.38   |
| NSA5356-8-13:F6198    | 219    | 50 | \$81.05  |
| NSA5359-6-15:F6198    | 17     | 50 | \$49.51  |
| ABS1344-104LZ04:FAPE3 | 74     | 50 | \$51.45  |
| ASNA0082-206Y:F6198   | 400    | 50 | \$2.50   |
| ASNA2001V4-7X:F6198   | 26     | 20 | \$249.59 |
| DAN5-10-7:D8518       | 116    | 50 | \$2.85   |
| DIN65399-2406BF:D8286 | 144550 | 50 | \$0.03   |
| EN6115K3-21:I9005     | 293    | 30 | \$21.73  |
| HL755VF6-5:92215      | 99     | 50 | \$10.81  |
| NAS1102E3R7:80205     | 760    | 20 | \$1.05   |
| NAS1352-3-10P:80205   | 1200   | 50 | \$2.80   |
| NSA5023-4-6:F6198     | 4699   | 20 | \$1.42   |
| NSA5486V9R23N:F6198   | 206    | 50 | \$34.66  |
| NSA855111C24:F6198    | 45     | 30 | \$86.78  |
| S22225CM050016:F0111  | 7      | 20 | \$48.99  |
| 3TLV946-7R27N:92215   | 14     | 50 | \$157.31 |
| ABS0394B100:FAPE3     | 4580   | 50 | \$5.68   |
| ABS1381-19F1214:FAPE3 | 31     | 50 | \$14.41  |
| ABS1745K4-8:FAPE3     | 108    | 50 | \$225.09 |
| ABS2187A132-52:FAPE3  | 40     | 50 | \$6.33   |
| DAN7-10-5X:D8518      | 471    | 50 | \$58.10  |
| DAN7-5-12:D8518       | 1160   | 50 | \$1.87   |
| EN6114T4-24:I9005     | 49     | 50 | \$3.82   |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| EN6115K3A20:I9005     | 59    | 20 | \$68.78  |
| EN6115T3AX7:I9005     | 324   | 30 | \$25.77  |
| EN6115T7-15:I9005     | 409   | 30 | \$7.24   |
| GTR71-20CACS1:06324   | 6     | 20 | \$42.81  |
| HL412VF10-8:C4293     | 17    | 50 | \$32.23  |
| HLT902BV8-4:73197     | 1958  | 50 | \$54.62  |
| MS21250-12042:96906   | 86    | 50 | \$76.52  |
| MS35206-225:96906     | 13450 | 50 | \$0.45   |
| ABS1081T16:FAPE3      | 5     | 50 | \$581.44 |
| ABS1115A028E450:FAPE3 | 94    | 50 | \$33.99  |
| AN737TW34:88044       | 128   | 50 | \$4.51   |
| ASNA0081-206Y:F6198   | 180   | 50 | \$3.79   |
| ASNA0093P8-17:F6198   | 474   | 50 | \$40.50  |
| EN6115M6-12:I9005     | 90    | 20 | \$28.73  |
| HL755VF5-8:92215      | 250   | 20 | \$1.01   |
| MS21076-06:96906      | 354   | 20 | \$2.20   |
| MS21141U0603P:96906   | 10    | 50 | \$57.50  |
| NSA5356-3-16:F6198    | 23    | 20 | \$7.76   |
| NSA5476BV5-8:F6198    | 471   | 50 | \$8.19   |
| DAN7-12-12X:D8518     | 281   | 50 | \$105.16 |
| EN2997RS60803A6:I9005 | 46    | 50 | \$34.11  |
| NAS1241AD3-12:80205   | 10085 | 20 | \$0.07   |
| NAS1611-322:80205     | 1082  | 20 | \$1.05   |
| NAS6206-31:80205      | 64    | 20 | \$11.94  |
| ABS0578-14:FAPE3      | 100   | 50 | \$118.75 |
| ABS0787E56C:FAPE3     | 99    | 50 | \$9.66   |
| AS43314:U1653         | 15    | 50 | \$14.98  |
| AS5169R04L:81343      | 23    | 50 | \$19.77  |
| ASNA2397KD4:F6198     | 3034  | 50 | \$0.09   |
| ASNA2634-207:F6198    | 107   | 50 | \$18.33  |
| EN6115K8-25:I9005     | 487   | 30 | \$14.81  |
| EN6115T5Y7:I9005      | 154   | 50 | \$35.33  |
| MS16624-5018:96906    | 2660  | 50 | \$0.19   |
| MS20470T8-12:96906    | 52    | 50 | \$8.34   |
| MS51861-47:96906      | 2175  | 50 | \$0.14   |
| MS9557-04:96906       | 530   | 20 | \$1.49   |
| NAS6305U20:80205      | 750   | 50 | \$8.72   |
| NSA5356-9-22:F6198    | 698   | 20 | \$68.25  |
| NSA5478BV5-8:F6198    | 1260  | 50 | \$8.37   |
| AS48550:U1653         | 9     | 30 | \$19.53  |
| AS5178D24:81343       | 638   | 50 | \$9.05   |
| ASNA3766-12A:F6198    | 2     | 20 | \$214.95 |
| DAN80-2-160:D8518     | 14    | 20 | \$12.53  |
| HL855VF8-15:C4293     | 40    | 50 | \$38.34  |
| M39029-9-134:81349    | 23    | 50 | \$13.69  |
| MBF2113S6-350:92215   | 195   | 50 | \$14.43  |
| MS24694C71:96906      | 125   | 20 | \$2.11   |
| MS9048-038:96906      | 480   | 50 | \$1.41   |
| MS9386-109:96906      | 585   | 50 | \$0.20   |
| MS9581-11:96906       | 133   | 50 | \$2.55   |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| NAS1153V13A:80205     | 50    | 50 | \$3.88   |
| NAS1305-38:80205      | 405   | 30 | \$1.56   |
| NSA5119A14-496:F6198  | 5     | 20 | \$933.35 |
| NSA5478VHK5-8:F6198   | 212   | 50 | \$60.61  |
| NSA5479VHK5-13Y:F6198 | 28    | 20 | \$149.72 |
| NSA937901E16:F6198    | 58    | 50 | \$0.84   |
| ABS0396C56SA:FAPE3    | 100   | 50 | \$12.72  |
| ABS0744-48M:FAPE3     | 39    | 50 | \$206.72 |
| ABS1190B40L170K:FAPE3 | 10    | 50 | \$429.79 |
| ABS1360-08-09B:FAPE3  | 11    | 50 | \$81.42  |
| ABS1660A175A1G:FAPE3  | 20    | 50 | \$15.96  |
| AS3582-006:81343      | 1134  | 50 | \$0.31   |
| ASNA3757G242406:F6198 | 11    | 50 | \$280.87 |
| E0165D11A163X:F6198   | 10    | 50 | \$566.35 |
| EN6114K8-31:I9005     | 500   | 50 | \$17.89  |
| EN6115V8-5:I9005      | 571   | 50 | \$19.39  |
| MS24392J6:96906       | 40    | 50 | \$11.10  |
| NAS1330H06K106L:80205 | 428   | 20 | \$2.23   |
| NSA5159-23P:F6198     | 494   | 50 | \$8.34   |
| NSA5479BV6-25Y:F6198  | 86    | 50 | \$45.01  |
| NSA855020-8:F6198     | 12    | 30 | \$61.73  |
| 15S11-1AC:D0680       | 260   | 50 | \$1.06   |
| ASNA0143A9N25:F6198   | 136   | 50 | \$64.40  |
| EN6081D4-06-5:I9005   | 81514 | 50 | \$0.02   |
| EN6115-3X5:I9005      | 325   | 50 | \$8.07   |
| EN6115K4-21:I9005     | 796   | 20 | \$3.93   |
| EN6115T7-26:I9005     | 298   | 20 | \$6.88   |
| MS21250-07016:96906   | 42    | 50 | \$19.29  |
| NAS602-5B:80205       | 1820  | 50 | \$0.21   |
| ABS1265A016B600:FAPE3 | 96    | 50 | \$138.09 |
| EN6101KE5-05:I9005    | 2324  | 20 | \$0.45   |
| M25988-4-031:81349    | 530   | 50 | \$1.53   |
| MS21909W10:96906      | 23    | 30 | \$55.02  |
| NAS623-4-16:80205     | 250   | 20 | \$0.76   |
| NSA5120-5-055:F6198   | 14    | 50 | \$5.70   |
| NSA5357-6-20:F6198    | 6     | 50 | \$71.43  |
| NSA5398-10-22A:F6198  | 117   | 20 | \$178.69 |
| 363057:D1227          | 170   | 50 | \$6.44   |
| 3TL946-10-29N:73197   | 2     | 50 | \$76.00  |
| A228G14X:K7766        | 10    | 50 | \$121.55 |
| ABS0743T5-32:FAPE3    | 6     | 50 | \$193.11 |
| ABS1114B020D500:FAPE3 | 42    | 50 | \$148.85 |
| ABS1500H2170AJ:FAPE3  | 15    | 50 | \$31.44  |
| EN6114K10-34:I9005    | 55    | 50 | \$161.96 |
| G51HA:03296           | 200   | 20 | \$0.98   |
| MS20470AD6-13:96906   | 16932 | 50 | \$0.15   |
| MS21908K4:96906       | 6     | 20 | \$40.98  |
| NAS1802-4-19:80205    | 350   | 50 | \$2.70   |
| NAS623-4-2:80205      | 2016  | 50 | \$0.22   |
| NAS6303U4D:80205      | 439   | 50 | \$7.03   |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| NAS6403A3:80205       | 340   | 50 | \$2.95   |
| NAS6704U67:80205      | 854   | 50 | \$6.61   |
| NSA5350V6-24:F6198    | 9     | 50 | \$162.37 |
| NSA8203-440:F6198     | 100   | 50 | \$45.49  |
| ABS0935-10:FAPE3      | 16    | 50 | \$13.48  |
| ASNA2016T3-2:F6198    | 1000  | 30 | \$4.51   |
| E0053R8B3APNF:F5442   | 8     | 50 | \$37.75  |
| E0466TS0607:F6198     | 14    | 50 | \$34.27  |
| EN6115K6-19:I9005     | 440   | 50 | \$5.31   |
| HL11V8-9:73197        | 100   | 20 | \$4.87   |
| L21217040015DEJ:F0111 | 550   | 50 | \$0.69   |
| MS16625-1068:96906    | 950   | 50 | \$0.69   |
| MS9062-13:96906       | 136   | 20 | \$4.99   |
| NAS1241D6-12:80205    | 813   | 50 | \$0.07   |
| NAS1720H5-2A:80205    | 200   | 20 | \$1.06   |
| NAS43DD4-32FC:80205   | 60    | 20 | \$10.95  |
| NAS561SF3-9:80205     | 1461  | 50 | \$0.51   |
| NSA5089-7D44:F6198    | 53    | 20 | \$199.76 |
| NSA5306-14:F6198      | 112   | 50 | \$321.96 |
| E0617B13N:F6198       | 201   | 50 | \$7.84   |
| HL110VF8-18:92215     | 330   | 20 | \$9.47   |
| HLT901BV20-28:73197   | 8     | 50 | \$277.15 |
| NAS1671-3L4:80205     | 142   | 50 | \$9.92   |
| NAS602-28P:80205      | 803   | 50 | \$0.33   |
| NAS6607-18:80205      | 80    | 50 | \$3.76   |
| NAS8303-12:80205      | 1617  | 50 | \$0.50   |
| NSA5042V04-260:F6198  | 71    | 20 | \$11.45  |
| NSA5120CR9-115:F6198  | 100   | 30 | \$25.83  |
| NSA5407-32-012R:F6198 | 11479 | 50 | \$0.58   |
| NSA5482PN8-30:F6198   | 47    | 50 | \$149.65 |
| ABS0114V4D42:FAPE3    | 2     | 50 | \$81.48  |
| ABS1172A120J:FAPE3    | 7     | 50 | \$68.75  |
| AN03M96:F4814         | 10    | 50 | \$68.37  |
| ASNA2151-06:F6198     | 8     | 50 | \$119.42 |
| CR3253-6-07:11815     | 217   | 50 | \$2.30   |
| E0217XVX2501A:F6198   | 13    | 20 | \$679.62 |
| EN6114T4Y10:I9005     | 103   | 50 | \$31.40  |
| HL412VF10-6:C4293     | 399   | 50 | \$89.30  |
| MS20426AD3-4A:96906   | 3536  | 20 | \$0.60   |
| NAS1790C3R9:80205     | 269   | 50 | \$4.24   |
| NSA5477BV3-2:F6198    | 1016  | 50 | \$61.11  |
| ABS1464T08:FAPE3      | 9     | 50 | \$225.68 |
| ASNA0093-8-24:F6198   | 48    | 20 | \$139.75 |
| ASNA2026VHK6-13:F6198 | 820   | 20 | \$7.86   |
| E0110R22B55PN:F5442   | 7     | 30 | \$117.99 |
| NAS1068A5:80205       | 160   | 20 | \$3.64   |
| NAS1133E22:80205      | 88    | 20 | \$7.10   |
| NAS1351C08H8P:80205   | 252   | 20 | \$2.99   |
| NAS6706U14:80205      | 255   | 50 | \$2.78   |
| NSA5359-4-5:F6198     | 14    | 50 | \$30.17  |

|                       |       |    |          |
|-----------------------|-------|----|----------|
| ASNA0096-8-14:F6198   | 2     | 50 | \$835.07 |
| EN6076-02:I9005       | 1376  | 50 | \$9.83   |
| EN6115V6-2:I9005      | 542   | 50 | \$2.92   |
| MS25281R9:96906       | 390   | 30 | \$2.25   |
| MS51958-70:96906      | 630   | 20 | \$0.45   |
| MS90354U0504:96906    | 3356  | 50 | \$1.39   |
| NAS1149E1290P:80205   | 45    | 30 | \$2.78   |
| NSA5089-6-28:F6198    | 1     | 50 | \$139.03 |
| ASNA3752D121010:F6198 | 18    | 20 | \$80.39  |
| E0186R18S31-01:F5442  | 8     | 50 | \$25.16  |
| EN6114-4Y7:I9005      | 220   | 20 | \$16.13  |
| EN6115-3-9:I9005      | 675   | 30 | \$1.62   |
| HLT951PN14-24:73197   | 462   | 50 | \$22.29  |
| MS16625-4112:96906    | 433   | 30 | \$1.09   |
| MS20470D5-12:96906    | 200   | 50 | \$0.91   |
| MS51957-60:96906      | 1139  | 50 | \$5.22   |
| MS9276-16:96906       | 720   | 20 | \$1.10   |
| NAS463XD416L:80205    | 6400  | 50 | \$0.18   |
| NAS517-2-00:80205     | 1730  | 50 | \$0.09   |
| NSA5031-4-23:F6198    | 1048  | 50 | \$2.72   |
| NSA5516CA48ND:F6198   | 30    | 20 | \$2.15   |
| MS171497:96906        | 1304  | 50 | \$0.60   |
| MS21904V12P:96906     | 16    | 50 | \$473.03 |
| NAS1102V3-13A:80205   | 16    | 20 | \$2.21   |
| NAS1580A3T7X:80205    | 1301  | 50 | \$0.63   |
| NAS1803-3B11:80205    | 171   | 50 | \$8.19   |
| NAS514P832-22:80205   | 1636  | 50 | \$0.56   |
| NSA5476VHK4-13:F6198  | 360   | 50 | \$1.05   |
| NSA5477BV5-22:F6198   | 410   | 50 | \$340.78 |
| ABS0582V12-14P:FAPE3  | 26    | 50 | \$28.78  |
| ASNA0077A602:F6198    | 500   | 20 | \$1.48   |
| ASNA3757E101006:F6198 | 10    | 30 | \$176.09 |
| EN2997KE61407BN:I9005 | 16    | 20 | \$38.70  |
| HL412VF8-13:92215     | 6     | 50 | \$137.74 |
| M25988-3-021:81349    | 100   | 30 | \$4.46   |
| MS14144L14:96906      | 109   | 20 | \$61.28  |
| MS20426D3-7:96906     | 13228 | 50 | \$0.07   |
| MS20615-5M14:96906    | 400   | 20 | \$0.98   |
| NAS1198-5-7:80205     | 580   | 50 | \$0.36   |
| NAS1351C4H14P:80205   | 95    | 20 | \$18.34  |
| NAS1611-217:80205     | 1189  | 50 | \$2.05   |
| NAS620-6L:80205       | 2979  | 50 | \$0.02   |
| NAS6607D29:80205      | 102   | 50 | \$5.05   |
| NAS6704HU25:80205     | 133   | 50 | \$8.32   |
| ABS1263A75250WG:FAPE3 | 1     | 50 | \$354.64 |
| EN6101KE6-09:I9005    | 16264 | 50 | \$0.18   |
| HL10VBJ5-4:73197      | 149   | 50 | \$3.36   |
| M81935-1-14K:81349    | 6     | 50 | \$116.36 |
| MS35190-213:96906     | 1419  | 50 | \$2.80   |
| MS35206-235:96906     | 8008  | 50 | \$0.25   |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| NAS1134-7:80205       | 74    | 50 | \$0.93   |
| NAS1352C04H4:80205    | 405   | 20 | \$1.44   |
| NAS6603H10:80205      | 567   | 20 | \$2.01   |
| NSA5356-7-22:F6198    | 29    | 50 | \$52.42  |
| 21217DC3215J:F0111    | 205   | 50 | \$0.18   |
| ABS1051B027340D:FAPE3 | 5     | 50 | \$51.48  |
| ABS1150H16-001:FAPE3  | 1     | 50 | \$221.97 |
| ABS1339F01:FAPE3      | 43    | 50 | \$2.87   |
| ASNA2004V3-5:F6198    | 51    | 20 | \$373.78 |
| E0237E15S02A:F5442    | 40    | 20 | \$25.24  |
| EN6114K3X19:I9005     | 5     | 30 | \$6.83   |
| HST1087-8:73197       | 84    | 50 | \$5.41   |
| MS20033-2:96906       | 243   | 50 | \$5.72   |
| MS21059L08K:96906     | 4492  | 50 | \$0.29   |
| MS35207-272:96906     | 740   | 30 | \$0.55   |
| NAS1080R05:80205      | 50    | 20 | \$0.89   |
| NAS1101E3-6:80205     | 1087  | 50 | \$1.07   |
| NAS1352-04H4P:80205   | 204   | 50 | \$0.88   |
| NAS6205-5:80205       | 495   | 50 | \$0.91   |
| NAS6709DU30:80205     | 9     | 20 | \$62.39  |
| NSA5357-5-8:F6198     | 29    | 50 | \$34.70  |
| A102-32J:K7766        | 39    | 50 | \$11.45  |
| ABS1340D28-06NF:FAPE3 | 3     | 50 | \$282.32 |
| ABS1509A140NN:FAPE3   | 5     | 50 | \$7.45   |
| ASNA0143A4N7:F6198    | 66    | 50 | \$13.52  |
| ASNA2721B3-8:F6198    | 280   | 50 | \$0.67   |
| CR3212-6-11:11815     | 72    | 30 | \$3.28   |
| CR3253-6-06:11815     | 140   | 50 | \$1.97   |
| EN6114-12Y48:I9005    | 120   | 50 | \$223.61 |
| EN6114-4Y8:I9005      | 105   | 50 | \$5.47   |
| HL112VF6-15:92215     | 982   | 50 | \$5.68   |
| HLT901KN8-5:60516     | 323   | 50 | \$16.92  |
| MBF2111S6-200:92215   | 150   | 20 | \$223.68 |
| MS16632-4023:96906    | 1923  | 50 | \$0.14   |
| MS171524:96906        | 3754  | 50 | \$0.15   |
| NAS561C4-12:80205     | 1531  | 20 | \$0.39   |
| NAS6205-19:80205      | 350   | 50 | \$0.62   |
| NAS6603-48:80205      | 139   | 50 | \$4.55   |
| NAS6708DU32:80205     | 30    | 20 | \$20.24  |
| NSA5356-10-32:F6198   | 194   | 50 | \$47.79  |
| NSA5476BV10-16:F6198  | 500   | 30 | \$43.01  |
| NSA855034G08:F6198    | 5     | 50 | \$6.04   |
| NSA933667-01-5:F6198  | 30    | 50 | \$132.48 |
| ABS1028C00EA502:FAPE3 | 15    | 50 | \$612.65 |
| ABS1114C016D300:FAPE3 | 31    | 50 | \$188.18 |
| ABS1359-12-12B:FAPE3  | 13    | 50 | \$895.29 |
| ASNA2001V4-10X:F6198  | 36    | 20 | \$57.85  |
| EN6115T7-14:I9005     | 473   | 50 | \$7.52   |
| MS20470A5-8:96906     | 15432 | 50 | \$0.05   |
| NAS6604H22:80205      | 195   | 20 | \$3.78   |

|                       |      |    |          |
|-----------------------|------|----|----------|
| NAS6705-11:80205      | 168  | 50 | \$7.15   |
| NSA5479BV7-42:F6198   | 10   | 50 | \$24.88  |
| AS5169J03L:81343      | 45   | 50 | \$7.55   |
| ASNA2000V4D10:F6198   | 136  | 50 | \$2.11   |
| EN6114K10Y31:I9005    | 101  | 30 | \$83.02  |
| EN6115T8-20:I9005     | 73   | 30 | \$10.44  |
| HLT908PB10-11:F0188   | 32   | 50 | \$36.84  |
| MS21141U0605PW:96906  | 1411 | 50 | \$1.54   |
| MS21904J12:96906      | 90   | 50 | \$47.79  |
| NAS1670-3DL7:80205    | 133  | 20 | \$3.88   |
| NSA5042-14A496:F6198  | 433  | 20 | \$36.73  |
| NSA5479VHK5-12Y:F6198 | 44   | 50 | \$368.96 |
| ABS1358-20-20B:FAPE3  | 86   | 50 | \$29.05  |
| ABS5098BER29-12:FAPE3 | 60   | 50 | \$2.61   |
| ASNA2026VHK5-6:F6198  | 450  | 50 | \$1.60   |
| EN6114-10Y37:I9005    | 42   | 20 | \$218.58 |
| MS18064-10:96906      | 382  | 20 | \$1.32   |
| MS21250-03009:96906   | 110  | 50 | \$1.12   |
| MS24665-143:96906     | 3100 | 50 | \$0.07   |
| NSA5042-10-325:F6198  | 44   | 20 | \$35.13  |
| NSA5399-5-20A:F6198   | 31   | 50 | \$30.89  |
| SL4086-04A:B1103      | 238  | 50 | \$1.02   |
| ABS0112-32-09T:FAPE3  | 1986 | 50 | \$0.51   |
| DAN8-8-16X:D8518      | 30   | 30 | \$4.44   |
| E0053R14B15SNFC:F5442 | 53   | 50 | \$66.49  |
| EN6114T6X25:I9005     | 1    | 50 | \$198.40 |
| EN6115K6Y9:I9005      | 21   | 50 | \$60.78  |
| MS20253P3-157L:96906  | 80   | 50 | \$14.49  |
| MS20426D5-14:96906    | 3199 | 50 | \$0.53   |
| NAS1399D5-7:80205     | 180  | 20 | \$3.66   |
| NAS1921M06S05W:80205  | 40   | 50 | \$2.08   |
| NAS4403-3:80205       | 1229 | 50 | \$0.61   |
| NAS6403U16:80205      | 246  | 50 | \$1.60   |
| NAS9302E4-07:80205    | 570  | 50 | \$1.34   |
| NSA5092V8-19:F6198    | 16   | 20 | \$118.94 |
| 3TL946-8-19N:73197    | 16   | 50 | \$583.80 |
| ABS1343D24-04NF:FAPE3 | 6    | 50 | \$258.28 |
| ABS2133M0808:FAPE3    | 99   | 50 | \$19.62  |
| AN3-10A:88044         | 450  | 50 | \$0.26   |
| CR3552P6-10:11815     | 20   | 20 | \$6.42   |
| MS35190-223:96906     | 3400 | 50 | \$0.14   |
| NAS1252-6L:80205      | 1773 | 50 | \$0.09   |
| NAS1303-18D:80205     | 260  | 50 | \$2.56   |
| NAS1790C4R5:80205     | 3970 | 50 | \$1.27   |
| NAS6204-2:80205       | 4573 | 50 | \$0.52   |
| NSA5477VHK3-10:F6198  | 24   | 50 | \$10.86  |
| ABS1263A61700WG:FAPE3 | 6    | 50 | \$273.13 |
| E0053R24B61SWF:F5442  | 95   | 20 | \$25.19  |
| HLT912BV10-10:92215   | 934  | 50 | \$23.72  |
| MS27183-4:96906       | 9000 | 20 | \$0.07   |



|                       |      |    |            |
|-----------------------|------|----|------------|
| NAS6704A9:80205       | 175  | 30 | \$2.05     |
| NSA5089-6D18:F6198    | 100  | 30 | \$8.99     |
| NSA5476VHK7-26:F6198  | 169  | 50 | \$20.23    |
| EN2997SE62239AN:I9005 | 2    | 20 | \$162.59   |
| EN6115-10X35:I9005    | 5    | 50 | \$1,662.99 |
| HLT857PB20-27:73197   | 8    | 50 | \$591.01   |
| MS20392-4C23:96906    | 436  | 50 | \$1.56     |
| MS21904-12:96906      | 6    | 50 | \$36.00    |
| MS24693S275:96906     | 5356 | 50 | \$0.38     |
| NAS1131-8:80205       | 462  | 20 | \$1.70     |
| NAS1352N08-12:80205   | 945  | 50 | \$0.81     |
| NSA5121C04-105:F6198  | 363  | 50 | \$3.62     |
| NSA5372PD616BX:F6198  | 6290 | 50 | \$0.18     |
| 3TLV946-7R28N:92215   | 1    | 50 | \$39.91    |
| ABS2044A10D018:FAPE3  | 50   | 50 | \$63.96    |
| AN735C8:88044         | 20   | 50 | \$4.85     |
| EN2997SE01203B7:I9005 | 4    | 50 | \$44.42    |
| EN3645M6JL20BA:I9005  | 23   | 20 | \$44.82    |
| MS20470DD6-14:96906   | 94   | 50 | \$6.16     |
| MS51923-164:96906     | 220  | 50 | \$0.41     |
| MS51957-59:96906      | 1765 | 50 | \$0.22     |
| MS9715-08:96906       | 78   | 50 | \$10.40    |
| NAS1102E6-12:80205    | 277  | 30 | \$3.27     |
| NAS6304U26D:80205     | 123  | 50 | \$6.09     |
| NSA5378A10-37:F6198   | 11   | 50 | \$130.41   |
| NSA5479BV10-22X:F6198 | 84   | 50 | \$129.32   |
| NSA8203-043:F6198     | 36   | 50 | \$6.85     |
| 277159-1:00779        | 62   | 50 | \$184.77   |
| AN919-7K:88044        | 1    | 50 | \$38.12    |
| ASNA2358T3-4:F6198    | 1225 | 30 | \$6.10     |
| HLT901BV6-4:73197     | 183  | 20 | \$8.07     |
| MS21140U0602:96906    | 60   | 20 | \$7.46     |
| MS90354-0506:96906    | 102  | 50 | \$1.92     |
| NAS1134E4P:80205      | 79   | 50 | \$2.68     |
| NAS1802-6-24:80205    | 75   | 20 | \$6.50     |
| NAS6204-11D:80205     | 840  | 30 | \$1.40     |
| NAS6703-38:80205      | 30   | 50 | \$14.48    |
| NAS6707DU19:80205     | 108  | 50 | \$14.35    |
| NSA5399-4-10:F6198    | 11   | 20 | \$68.13    |
| NSA5476VHK4-12:F6198  | 774  | 50 | \$0.82     |
| NSA5709-4:F6198       | 8    | 50 | \$1,034.08 |
| ABS2285-01:FAPE3      | 14   | 50 | \$84.03    |
| ASNA2001V5-5:F6198    | 95   | 20 | \$64.21    |
| ASNA2391-6-27:F6198   | 88   | 20 | \$78.42    |
| EN2997R512:I9005      | 11   | 50 | \$21.93    |
| HLT856PN6-6:F0188     | 100  | 50 | \$50.90    |
| MS21250-08016:96906   | 1029 | 30 | \$20.40    |
| NAS1801-08-37:80205   | 680  | 50 | \$1.95     |
| NAS603-32P:80205      | 375  | 50 | \$0.62     |
| NAS6709DU24:80205     | 40   | 50 | \$36.26    |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| ABS0114T7D29:FAPE3    | 88    | 50 | \$13.71  |
| ABS0114V3-22:FAPE3    | 254   | 50 | \$2.59   |
| ABS0513-14:FAPE3      | 47    | 50 | \$15.36  |
| ABS1380-18M1214:FAPE3 | 58    | 50 | \$10.42  |
| AN833-8D:88044        | 50    | 50 | \$138.29 |
| DHS781-23-16:U1598    | 14    | 50 | \$2.52   |
| EN6115K7Y25:I9005     | 59    | 50 | \$101.82 |
| HL412VF8-2:C4293      | 354   | 50 | \$9.94   |
| MS21140S0504W:96906   | 105   | 20 | \$193.05 |
| MS21250-06019:96906   | 130   | 30 | \$6.30   |
| MS21916W4-2:96906     | 15    | 20 | \$32.55  |
| NAS1103-5:80205       | 1500  | 20 | \$0.14   |
| NAS1149D0632H:80205   | 11632 | 50 | \$0.07   |
| NAS1306-34:80205      | 290   | 20 | \$2.21   |
| NAS600-24P:80205      | 1900  | 20 | \$0.09   |
| NAS623-2-5:80205      | 3963  | 50 | \$0.27   |
| NSA5042-08-391:F6198  | 100   | 50 | \$19.67  |
| NSA5356-10-34:F6198   | 42    | 20 | \$150.58 |
| NSA5356-8-26:F6198    | 97    | 50 | \$45.94  |
| NSA5358-6-7:F6198     | 92    | 20 | \$85.89  |
| NSA5479BV5-7X:F6198   | 56    | 20 | \$35.28  |
| ABS1057-08A01:FAPE3   | 24    | 50 | \$38.19  |
| EN2997SE01203B9:I9005 | 3     | 50 | \$36.36  |
| EN6081D4X05:I9005     | 1702  | 20 | \$0.45   |
| EN6115-4X9:I9005      | 77    | 20 | \$5.97   |
| MS24693S294:96906     | 250   | 50 | \$0.14   |
| MS24693S6:96906       | 15043 | 50 | \$0.05   |
| MS51865-3:96906       | 78    | 50 | \$18.86  |
| NAS1611-006A:80205    | 175   | 50 | \$0.49   |
| NAS1792C3-5:80205     | 2451  | 50 | \$2.55   |
| NAS1992T5PT:80205     | 280   | 20 | \$2.16   |
| NAS6603-1X:80205      | 75    | 20 | \$31.01  |
| NSA5516CA14NF:F6198   | 600   | 20 | \$1.20   |
| NSA855113-29D:F6198   | 55    | 50 | \$53.08  |
| AN960JD10M:88044      | 2547  | 50 | \$0.07   |
| AS48618:U1653         | 40    | 20 | \$22.48  |
| ASNA2001V4D5:F6198    | 190   | 50 | \$14.41  |
| DAN257-32111:D8518    | 1600  | 30 | \$0.18   |
| DHS1906-6:U1598       | 16    | 50 | \$6.75   |
| EN3662-006A25AA:I9005 | 1     | 50 | \$564.84 |
| M25988-4-122:81349    | 60    | 50 | \$2.18   |
| M39029-101-553:81349  | 184   | 50 | \$0.94   |
| MS20470AD5-15:96906   | 1467  | 50 | \$0.19   |
| MS27039-4-12:96906    | 500   | 30 | \$0.31   |
| NAS1304-20D:80205     | 845   | 50 | \$5.10   |
| NAS1330S08-106:80205  | 1202  | 30 | \$0.34   |
| NAS623-5-11:80205     | 463   | 50 | \$1.42   |
| NAS6403A8:80205       | 84    | 20 | \$3.47   |
| NAS6603-50X:80205     | 77    | 20 | \$111.16 |
| NSA5042C04-183:F6198  | 95    | 50 | \$14.60  |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| NSA5477VHK8-15:F6198  | 12    | 50 | \$143.01 |
| NSA5480PN10-29:F6198  | 2     | 20 | \$61.48  |
| HL13VF5-11:92215      | 70    | 20 | \$1.25   |
| HL19PB5-4:92215       | 158   | 50 | \$1.38   |
| MS20392-3R79:96906    | 38    | 20 | \$18.31  |
| NAS1351C4H24:80205    | 164   | 20 | \$4.32   |
| NAS1611-158A:80205    | 80    | 50 | \$8.19   |
| ABS0783B03C:FAPE3     | 157   | 50 | \$12.56  |
| DAN8-8-2:D8518        | 4592  | 50 | \$3.35   |
| EN6115-8-23:I9005     | 209   | 50 | \$12.40  |
| MS17984C407:96906     | 5     | 50 | \$34.70  |
| MS21049-3:96906       | 56    | 50 | \$1.08   |
| MS9320-12:96906       | 1575  | 50 | \$0.25   |
| MS9519-07:96906       | 70    | 50 | \$3.17   |
| NAS1080C06:80205      | 6709  | 20 | \$0.07   |
| NAS1100E04-5:80205    | 1420  | 50 | \$0.51   |
| NAS4404-11:80205      | 100   | 20 | \$2.13   |
| NSA5191-3V43:F6198    | 19    | 50 | \$12.03  |
| NSA5356-10-36:F6198   | 96    | 20 | \$47.96  |
| NSA5479BV3-7X:F6198   | 25    | 20 | \$31.57  |
| NSA5479BV4-9:F6198    | 843   | 50 | \$48.91  |
| NSA5479BV5-13:F6198   | 57    | 50 | \$6.95   |
| ASNA2391-2-03:F6198   | 672   | 50 | \$1.71   |
| E0052R24B61SWF:F5442  | 19    | 50 | \$76.04  |
| E0455-03-10N:F5442    | 5     | 50 | \$63.25  |
| HLT901KN8-10:73197    | 55    | 50 | \$24.90  |
| MBF2111S7-150:92215   | 50    | 50 | \$29.31  |
| MS21250H05038:96906   | 44    | 50 | \$12.34  |
| MS21250H07024:96906   | 45    | 20 | \$131.29 |
| MS9593-010:96906      | 122   | 20 | \$5.82   |
| NAS6606H9:80205       | 254   | 50 | \$12.95  |
| NAS6704U30:80205      | 485   | 50 | \$8.46   |
| E0663-02:F5442        | 12    | 20 | \$16.23  |
| EN2997RS61006B6:I9005 | 18    | 20 | \$33.55  |
| NAS1242D5-7:80205     | 18370 | 50 | \$0.50   |
| NAS514P428-10:80205   | 900   | 50 | \$0.62   |
| NAS6703-32:80205      | 125   | 20 | \$6.02   |
| NSA5378-7A28:F6198    | 4     | 50 | \$36.55  |
| NSA5398-5-22A:F6198   | 62    | 20 | \$437.73 |
| PLT215-8-6:98524      | 200   | 50 | \$4.56   |
| ABS0114T3-35:FAPE3    | 243   | 50 | \$11.06  |
| ABS0114V4D4:FAPE3     | 404   | 50 | \$5.78   |
| AS5169D08:81343       | 70    | 50 | \$5.72   |
| HL755VF8-6:92215      | 180   | 50 | \$49.03  |
| MS20470AD4-3:96906    | 6355  | 50 | \$0.02   |
| NAS1399D5-5:80205     | 133   | 50 | \$1.29   |
| NAS1921M05S07:80205   | 18    | 50 | \$300.30 |
| NAS6703-6X:80205      | 727   | 20 | \$8.37   |
| SP127NY:K5640         | 57    | 50 | \$10.21  |
| ASNA2392-3-11:F6198   | 495   | 50 | \$1.92   |

|                       |       |    |            |
|-----------------------|-------|----|------------|
| CR7684S05-03:11815    | 1900  | 50 | \$7.76     |
| E0165D17A03X:F6198    | 19    | 50 | \$817.26   |
| EN6114T7-4:I9005      | 91    | 50 | \$29.03    |
| EN6115T5-13:I9005     | 60    | 50 | \$2.69     |
| MS20615-5M3:96906     | 1014  | 20 | \$0.22     |
| MS21921-16J:96906     | 191   | 50 | \$20.61    |
| ASNA0093P10-26:F6198  | 107   | 20 | \$103.63   |
| E0091-08-250:F5442    | 410   | 50 | \$2.04     |
| E0165D13A27X:F5442    | 14    | 20 | \$488.48   |
| EN6081D6-12-5:I9005   | 6287  | 50 | \$0.09     |
| EN6115T6-8:I9005      | 96    | 30 | \$4.42     |
| HL633-5-21:73197      | 490   | 50 | \$28.66    |
| HLT908PB6-5:F0188     | 31    | 50 | \$4.44     |
| MS9549-10:96906       | 1150  | 20 | \$12.97    |
| NAS1635-3-8:80205     | 185   | 50 | \$0.53     |
| NAS623-4-4:80205      | 1230  | 20 | \$0.22     |
| NSA5159-18:F6198      | 365   | 50 | \$8.74     |
| NSA5305-6E:F6198      | 21    | 50 | \$6.28     |
| NSA5357-5-10:F6198    | 1278  | 20 | \$50.81    |
| ABS0060-133:FAPE3     | 89    | 50 | \$17.85    |
| ASNA2001V3-7Y:F6198   | 20    | 50 | \$49.47    |
| ASNA2016V4-26:F6198   | 12    | 50 | \$46.68    |
| EN6069KE5-05-5:I9005  | 12556 | 50 | \$0.12     |
| EN6114-18X29:I9005    | 12    | 20 | \$3,795.91 |
| EN6122C06-16H:I9005   | 997   | 20 | \$40.10    |
| HL755VF6-2:FAPE3      | 80    | 50 | \$1.08     |
| MS35489-12S:96906     | 500   | 50 | \$2.95     |
| MS9696-05:96906       | 85    | 20 | \$4.91     |
| NAS686A4:80205        | 359   | 50 | \$1.17     |
| NSA5487V8R27N:F6198   | 141   | 50 | \$126.43   |
| PE20001D20:F6087      | 8     | 20 | \$764.84   |
| ABS0114-4-12:FAPE3    | 457   | 50 | \$5.92     |
| ABS0114V4D5:FAPE3     | 727   | 50 | \$3.77     |
| ABS0744-32M:FAPE3     | 128   | 50 | \$118.13   |
| ABS1700AF0720XB:FAPE3 | 49    | 50 | \$1,087.93 |
| ASNA0009A600:F6198    | 2     | 50 | \$19.36    |
| MS21915J5-4:96906     | 220   | 50 | \$160.52   |
| NAS1304-44:80205      | 102   | 50 | \$2.03     |
| NSA5023-3D9:F6198     | 54    | 50 | \$10.14    |
| NSA5089-9D62:F6198    | 29    | 20 | \$172.36   |
| NSA5476BV3-14:F6198   | 900   | 50 | \$1.25     |
| AN3H4A:88044          | 63    | 50 | \$1.09     |
| ASNA2176:F5442        | 2     | 50 | \$4,254.82 |
| EN3645W3B0:I9005      | 10    | 50 | \$31.71    |
| EN6114T5X14:I9005     | 8     | 30 | \$29.34    |
| EN6114V8-8:I9005      | 123   | 20 | \$16.04    |
| EN6115T8-21:I9005     | 78    | 50 | \$10.76    |
| HL110VF8-22:92215     | 390   | 20 | \$14.67    |
| HLT856PB8-8:F0188     | 91    | 20 | \$46.50    |
| HLT901BV10-11:73197   | 30    | 50 | \$110.63   |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| NAS514P832-11P:80205  | 2248  | 20 | \$0.30   |
| NAS6703D19:80205      | 129   | 50 | \$9.78   |
| NAS674V2:80205        | 147   | 50 | \$4.99   |
| 2700-7:D0680          | 34    | 50 | \$9.66   |
| AS48529:U1653         | 25    | 50 | \$15.56  |
| ASNA0082-305Y:F6198   | 41    | 20 | \$1.68   |
| EN3646RS62221AN:I9005 | 18    | 20 | \$45.07  |
| HL11VF6-15:92215      | 40    | 50 | \$10.19  |
| NAS7903A3:80205       | 454   | 30 | \$3.19   |
| NSA5042-08-425:F6198  | 192   | 50 | \$20.75  |
| NSA5121-05-070:F6198  | 102   | 50 | \$3.40   |
| NSA5153VA6-16:F6198   | 1     | 50 | \$27.88  |
| NSA5357-6-17:F6198    | 64    | 50 | \$48.17  |
| EN6114K2-10:I9005     | 126   | 50 | \$3.59   |
| HL856VF6-9:73197      | 341   | 50 | \$17.06  |
| LK39516:K0680         | 45    | 20 | \$19.06  |
| MS14218AD4-7:96906    | 2161  | 50 | \$0.25   |
| MS9923-05:96906       | 543   | 20 | \$4.56   |
| NSA855114-67:F6198    | 100   | 20 | \$291.43 |
| NSA9501-100:F6198     | 6     | 30 | \$93.63  |
| ABS0113-10-23X:FAPE3  | 4     | 50 | \$164.45 |
| EN6081D5X06-5:I9005   | 140   | 50 | \$20.94  |
| MS171435:96906        | 7884  | 50 | \$0.14   |
| MS20470E6-11:96906    | 29100 | 50 | \$0.05   |
| MS21906J4:96906       | 28    | 50 | \$68.52  |
| MS27039-4-15:96906    | 980   | 20 | \$0.21   |
| MS51990-105P:96906    | 169   | 30 | \$5.12   |
| NAS623-4-5:80205      | 908   | 50 | \$0.61   |
| NSA5516CA17ND:F6198   | 1100  | 20 | \$0.67   |
| ABS0114V9D24:FAPE3    | 82    | 50 | \$22.96  |
| ASNA2001V6-17Y:F6198  | 28    | 20 | \$48.29  |
| ASNA3758-24:F6198     | 4     | 50 | \$179.42 |
| ASNA3764-1612:F6198   | 8     | 30 | \$182.78 |
| E0053R22B41PNF:F5442  | 98    | 20 | \$50.20  |
| HL11V5-2:73197        | 480   | 50 | \$1.56   |
| MS16562-190:96906     | 7190  | 50 | \$0.95   |
| MS20615-6M10:96906    | 54    | 20 | \$2.54   |
| NAS1097AD4-3:80205    | 49289 | 50 | \$0.02   |
| NAS1153V5P:80205      | 335   | 50 | \$0.70   |
| NAS6603H6:80205       | 70    | 50 | \$3.16   |
| NSA5120C4-040:F6198   | 176   | 20 | \$18.94  |
| ABS0554-76-1:FAPE3    | 2     | 50 | \$237.21 |
| ABS1095A01:FAPE3      | 477   | 50 | \$2.94   |
| ASNA2001T5-48:F6198   | 11    | 20 | \$80.93  |
| EN4165F15A:I9005      | 75    | 50 | \$4.79   |
| EN6115-3A4:I9005      | 9     | 20 | \$672.38 |
| EN6115K10X20:I9005    | 88    | 50 | \$807.62 |
| HLT901BV12-20:92215   | 62    | 50 | \$47.04  |
| LN9016-04L:D8442      | 2666  | 50 | \$2.24   |
| MS24693S4:96906       | 6300  | 50 | \$0.08   |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| NAS1241D6-14:80205    | 4494  | 50 | \$0.67   |
| NAS1801-3-60:80205    | 1888  | 50 | \$9.43   |
| NAS6304U12:80205      | 299   | 30 | \$1.73   |
| NAS6604D4:80205       | 657   | 50 | \$0.88   |
| NSA5042-05-105:F6198  | 30    | 50 | \$5.94   |
| NSA5121C04-200:F6198  | 599   | 20 | \$11.96  |
| NSA5359-7-27:F6198    | 126   | 20 | \$156.58 |
| NSA5398-7-20A:F6198   | 97    | 20 | \$52.80  |
| EN6114-12-17:I9005    | 27    | 20 | \$982.44 |
| HL10VF8-22:92215      | 440   | 20 | \$18.77  |
| NAS623-5-20:80205     | 100   | 50 | \$1.15   |
| NSA937903E:F6198      | 23    | 20 | \$45.22  |
| ABS0114V3-4X:FAPE3    | 270   | 50 | \$6.14   |
| ABS0783D52C:FAPE3     | 96    | 50 | \$12.56  |
| ASNA0078F605:F6198    | 2241  | 20 | \$0.70   |
| EN6081D6-10-5:I9005   | 26744 | 50 | \$0.09   |
| HL10VAZ6-2:73197      | 217   | 30 | \$1.38   |
| MS21069L5:96906       | 841   | 50 | \$1.94   |
| NAS1097AD3-2:80205    | 42000 | 30 | \$0.02   |
| NAS1097KE5-8-5:80205  | 56395 | 50 | \$0.06   |
| NSA5041-3-16:F6198    | 1000  | 50 | \$4.24   |
| NSA5477VHK10-18:F6198 | 22    | 50 | \$186.31 |
| NSA931130-10S:F6198   | 53    | 20 | \$374.09 |
| ABS0564-0606A:FAPE3   | 3     | 50 | \$295.45 |
| ABS5483-3-013:FAPE3   | 22    | 50 | \$448.05 |
| ASNA0093-10-31:F6198  | 16    | 20 | \$51.14  |
| ASNA2041D3-04:F6198   | 808   | 30 | \$1.53   |
| ASNA2394E8:F6198      | 930   | 50 | \$9.50   |
| EN2997SE61006B7:I9005 | 10    | 20 | \$33.41  |
| EN3646RS02241BN:I9005 | 50    | 20 | \$68.74  |
| EN6114K3A16:I9005     | 789   | 20 | \$1.39   |
| EN6114V10-8:I9005     | 28    | 50 | \$18.94  |
| HL10V6-19:73197       | 27    | 50 | \$12.90  |
| HL111VAZ6-5:73197     | 63    | 50 | \$2.38   |
| HL13VF6-18:92215      | 710   | 50 | \$9.75   |
| HST12AP6-4:73197      | 14    | 30 | \$153.01 |
| MS28774-020:96906     | 111   | 20 | \$0.38   |
| NAS1580A3T5:80205     | 1910  | 50 | \$0.29   |
| NAS387-832-8P:80205   | 2200  | 20 | \$0.12   |
| NSA5120-5-045:F6198   | 99    | 50 | \$24.01  |
| NSA5378-5-24:F6198    | 10    | 20 | \$947.23 |
| ABS0738-2-26:FAPE3    | 44    | 50 | \$63.96  |
| ABS1577A04:FAPE3      | 100   | 50 | \$28.63  |
| ABS2225A09-03:FAPE3   | 83    | 50 | \$83.21  |
| AN814-4SL:88044       | 45    | 50 | \$19.39  |
| ASNA0096-10-32:F6198  | 60    | 20 | \$488.84 |
| ASNA2025-7:F6198      | 575   | 50 | \$1.42   |
| EN6115K6-26:I9005     | 10    | 50 | \$8.35   |
| HLT900BV6-11:73197    | 1250  | 50 | \$2.61   |
| M25988-3-212:81349    | 50    | 50 | \$1.85   |



|                       |       |    |            |
|-----------------------|-------|----|------------|
| MS24693C298:96906     | 5400  | 50 | \$0.24     |
| MS9581-15:96906       | 3     | 20 | \$191.21   |
| NAS1242AD5-10:80205   | 1399  | 20 | \$0.09     |
| NAS673V6:80205        | 932   | 20 | \$2.61     |
| NSA5317-3:F6198       | 155   | 50 | \$5.21     |
| NSA5358-8-21:F6198    | 17    | 50 | \$98.89    |
| NSA5479BV5-28:F6198   | 390   | 20 | \$20.94    |
| ABS0696X2-2-12:FAPE3  | 53    | 50 | \$25.31    |
| EN6069AD8-24:I9005    | 20    | 30 | \$1.65     |
| EN6115K9X44:I9005     | 9     | 50 | \$649.32   |
| HST12AP8-5:73197      | 20    | 50 | \$62.10    |
| MS20470AD4-5A:96906   | 42077 | 50 | \$0.03     |
| MS35335-32:96906      | 250   | 20 | \$0.19     |
| MS51957-36:96906      | 9658  | 50 | \$0.48     |
| NAS1204-22:80205      | 570   | 20 | \$1.17     |
| NSA5089-6D17:F6198    | 79    | 20 | \$9.42     |
| NSA5378A8-24:F6198    | 239   | 20 | \$66.31    |
| NSA5478BV5-24:F6198   | 299   | 50 | \$24.42    |
| ABS0114V4D29:FAPE3    | 428   | 50 | \$26.17    |
| ABS1359-14-12B:FAPE3  | 20    | 50 | \$62.87    |
| ABS1587T03:FAPE3      | 6     | 50 | \$2,252.68 |
| ABS1876-04:FAPE3      | 1     | 50 | \$957.12   |
| DA20961:F3132         | 28    | 30 | \$5.66     |
| EN6115K5Y21:I9005     | 21    | 30 | \$11.55    |
| LN9499-01045:D8442    | 570   | 50 | \$0.39     |
| MBF2113S7-250:92215   | 40    | 20 | \$71.85    |
| MS35276-261:96906     | 1685  | 20 | \$0.31     |
| NAS1149EN432P:80205   | 3739  | 20 | \$0.21     |
| NAS1241AD5-5:80205    | 5967  | 50 | \$0.05     |
| NAS1303-7H:80205      | 560   | 20 | \$1.08     |
| NAS603-13:80205       | 1664  | 50 | \$0.27     |
| NSA5042V07-296:F6198  | 155   | 30 | \$12.37    |
| ABS0650-12:FAPE3      | 7     | 50 | \$144.23   |
| ABS0898AN289:FAPE3    | 46    | 50 | \$408.61   |
| ABS1153C08-02:FAPE3   | 867   | 50 | \$1.50     |
| ABS1389T1608:FAPE3    | 10    | 50 | \$393.46   |
| AN960PD416:88044      | 700   | 50 | \$0.09     |
| MS20470E6-20:96906    | 4023  | 50 | \$0.20     |
| NAS1149D1165J:80205   | 998   | 20 | \$0.16     |
| NAS6708U14:80205      | 60    | 30 | \$9.92     |
| NSA5325-4:F6198       | 50    | 50 | \$26.29    |
| NSA5378-14-98:F6198   | 9     | 50 | \$1,093.07 |
| NSA5478BV4-16:F6198   | 922   | 50 | \$11.98    |
| NSA5479BV6-10X:F6198  | 5     | 20 | \$51.58    |
| NSA933611-01-83:F6198 | 15    | 20 | \$525.87   |
| ABS0114V4-16X:FAPE3   | 140   | 50 | \$84.19    |
| ASNA2314-4-10:F6198   | 37    | 50 | \$33.96    |
| ASNA2392-5-07:F6198   | 481   | 20 | \$3.08     |
| ASNA2394E7:F6198      | 14    | 20 | \$6.35     |
| EN6081D4-10-5:I9005   | 19721 | 50 | \$0.12     |

|                       |       |    |            |
|-----------------------|-------|----|------------|
| EN6101KE5-07:I9005    | 35871 | 50 | \$0.18     |
| EN6114-14Y24:I9005    | 48    | 20 | \$67.59    |
| EN6115-6-15:I9005     | 48    | 50 | \$80.02    |
| MS16995-12:96906      | 1620  | 50 | \$3.98     |
| MS20426D6-16:96906    | 39    | 50 | \$1.13     |
| MS21140S0505:96906    | 437   | 50 | \$9.82     |
| MS21902W24:96906      | 97    | 30 | \$38.92    |
| MS35207-281:96906     | 2940  | 50 | \$0.26     |
| NAS6704DU4:80205      | 864   | 50 | \$7.20     |
| NSA5121U10-195:F6198  | 100   | 20 | \$23.37    |
| A228G28X:K7766        | 40    | 50 | \$173.25   |
| EN3645M6EN20BN:I9005  | 42    | 20 | \$25.93    |
| NAS1198-5-8:80205     | 670   | 50 | \$0.36     |
| NAS1351N3-9S:80205    | 150   | 20 | \$3.86     |
| NAS6704A15:80205      | 208   | 50 | \$3.39     |
| NSA5603-8L:F6198      | 80    | 20 | \$2.75     |
| 22275BC040004L:F0542  | 438   | 50 | \$5.63     |
| ABS0873K4-8:FAPE3     | 1964  | 50 | \$2.76     |
| ABS1020C03B:FAPE3     | 92    | 50 | \$95.77    |
| ABS1835AAA06-01:FAPE3 | 10    | 50 | \$155.87   |
| EN6101KE5-11:I9005    | 2017  | 20 | \$0.38     |
| EN6115-5Y9:I9005      | 66    | 50 | \$47.88    |
| EN6115K3X15:I9005     | 413   | 20 | \$12.97    |
| MS21250-06030:96906   | 100   | 20 | \$17.75    |
| MS21919WDE9:96906     | 559   | 50 | \$1.76     |
| MS24264R14B7SN:96906  | 23    | 50 | \$73.40    |
| NAS1097AD4-11:80205   | 219   | 50 | \$3.45     |
| NAS6704D12:80205      | 979   | 30 | \$2.85     |
| NAS9302E5-05:80205    | 125   | 50 | \$1.41     |
| NSA5350-6-9:F6198     | 54    | 50 | \$49.95    |
| NSA5477BV10-28:F6198  | 43    | 50 | \$103.70   |
| NSA5479BV3-4X:F6198   | 233   | 50 | \$7.57     |
| NSA934201-01:F6198    | 56    | 20 | \$47.04    |
| ABS0107T075:FAPE3     | 8     | 50 | \$68.91    |
| ABS1359-08-09B:FAPE3  | 6     | 50 | \$351.78   |
| ABS1400L10CA251:FAPE3 | 10    | 50 | \$1,940.25 |
| ABS1660A125B1GB:FAPE3 | 36    | 50 | \$23.14    |
| ASNA0093-6-29:F6198   | 25    | 20 | \$324.92   |
| EN6115K3-25:I9005     | 65    | 20 | \$67.11    |
| HLT900BV6-9:73197     | 840   | 50 | \$2.70     |
| MS24694C60:96906      | 1590  | 50 | \$0.96     |
| NAS463XD10:80205      | 7500  | 50 | \$0.18     |
| NAS6706U12:80205      | 291   | 50 | \$11.45    |
| NAS697C06:80205       | 200   | 20 | \$1.27     |
| NSA5121CR07-275:F6198 | 1     | 20 | \$169.64   |
| NSA5356-8-28:F6198    | 15    | 50 | \$178.45   |
| NSA931320-075A:F6198  | 21    | 50 | \$8.67     |
| TY29M:F4957           | 144   | 50 | \$1.48     |
| ABS1263A75550WG:FAPE3 | 1     | 50 | \$357.50   |
| ABS2306E12FP1E:FAPE3  | 50    | 50 | \$16.83    |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| AS3578-212:81343      | 1715  | 50 | \$0.34   |
| EN3645M0JL20AA:I9005  | 4     | 20 | \$49.20  |
| HLT926AP14-27:73197   | 90    | 50 | \$47.79  |
| MS24693S53:96906      | 2278  | 50 | \$0.25   |
| MS51957-82:96906      | 898   | 20 | \$0.62   |
| NAS1304-23:80205      | 340   | 50 | \$2.34   |
| NAS514P832-22P:80205  | 1063  | 20 | \$0.65   |
| NAS6205-8:80205       | 385   | 50 | \$1.12   |
| NSA5023-4-2:F6198     | 60    | 20 | \$58.86  |
| ABS0650-06:FAPE3      | 6     | 50 | \$197.55 |
| AN4-22A:88044         | 300   | 50 | \$1.08   |
| EN6115-6X14:I9005     | 80    | 50 | \$47.53  |
| EN6115V3-25:I9005     | 955   | 20 | \$15.15  |
| MS21905W10:96906      | 4     | 30 | \$35.37  |
| MS21921-8D:96906      | 33    | 20 | \$4.48   |
| NAS1131-1:80205       | 98    | 50 | \$6.16   |
| NAS1351-4-18P:80205   | 910   | 50 | \$1.97   |
| NAS6203-36:80205      | 1030  | 20 | \$0.51   |
| NAS73-10E100:80205    | 7     | 20 | \$36.21  |
| NSA5478VHK5-16:F6198  | 361   | 50 | \$26.45  |
| EN6101KE7-20:I9005    | 107   | 50 | \$1.80   |
| EN6114L5-20:I9005     | 29    | 20 | \$93.87  |
| HLT926BV12-14:73197   | 13    | 50 | \$77.29  |
| MS21209F5-10:96906    | 1803  | 30 | \$0.78   |
| NAS1097AD3-7:80205    | 39    | 20 | \$10.50  |
| NAS1102E08-11:80205   | 158   | 50 | \$4.32   |
| NAS1726C6D:80205      | 95    | 50 | \$3.17   |
| NAS1801-3-43:80205    | 240   | 50 | \$1.20   |
| NAS509L10:80205       | 34    | 20 | \$7.29   |
| NAS6305U11:80205      | 3040  | 20 | \$3.04   |
| NAS6705D9:80205       | 143   | 50 | \$14.79  |
| NSA855111C12:F6198    | 41    | 50 | \$48.05  |
| ABS0548VHK4-19:FAPE3  | 63    | 50 | \$4.46   |
| ABS5098BER29-1:FAPE3  | 90    | 50 | \$9.61   |
| ASNA2352T4-6:F6198    | 280   | 50 | \$4.19   |
| EN6114K3A15:I9005     | 752   | 20 | \$2.92   |
| EN6114V9X19:I9005     | 3     | 50 | \$255.47 |
| M25988-3-215:81349    | 240   | 50 | \$1.26   |
| NAS603-28:80205       | 1038  | 20 | \$1.42   |
| NSA855113-34C:F6198   | 81    | 30 | \$36.55  |
| ABS1020C02B:FAPE3     | 242   | 50 | \$64.42  |
| ABS1185A10C11E3:FAPE3 | 7     | 50 | \$377.52 |
| E0545F09-35YA:F6198   | 224   | 20 | \$20.21  |
| MS14144-10:96906      | 5     | 20 | \$47.07  |
| MS20427M3-14:96906    | 2083  | 50 | \$0.34   |
| MS27183-10:96906      | 19367 | 50 | \$0.70   |
| NAS6204-42:80205      | 675   | 20 | \$1.01   |
| NAS6604D38:80205      | 310   | 50 | \$5.03   |
| ABS1418K9X23:FAPE3    | 197   | 50 | \$55.51  |
| ABS1660A250B1G:FAPE3  | 16    | 50 | \$21.52  |

|                       |      |    |          |
|-----------------------|------|----|----------|
| E0618A23N:F5442       | 24   | 20 | \$13.69  |
| EN2997RS61005BN:I9005 | 8    | 30 | \$61.80  |
| NAS1193K5-1:80205     | 55   | 50 | \$8.50   |
| NAS1611-118A:80205    | 1050 | 50 | \$3.38   |
| NAS6203-13:80205      | 1741 | 50 | \$0.42   |
| NAS6204-4:80205       | 1580 | 30 | \$0.43   |
| NSA5031-5D14:F6198    | 126  | 50 | \$7.66   |
| NSA5368-1216A:F6198   | 138  | 50 | \$6.16   |
| NSA5465-3-5:F6198     | 37   | 20 | \$19.37  |
| NSA5477BV4-20:F6198   | 973  | 50 | \$26.13  |
| NSA5479BV7-23X:F6198  | 86   | 50 | \$49.40  |
| ASNA2001V4-8X:F6198   | 511  | 20 | \$95.86  |
| ASNA2634-231:F6198    | 181  | 50 | \$31.44  |
| HL755VF6-3:92215      | 17   | 50 | \$22.21  |
| HLT901BV10-15:73197   | 49   | 20 | \$52.06  |
| MS20427M4-9:96906     | 268  | 20 | \$0.31   |
| MS27039-0821:96906    | 135  | 50 | \$0.48   |
| NAS1100-08-18:80205   | 964  | 50 | \$0.15   |
| NAS6704HU1:80205      | 357  | 50 | \$4.33   |
| NSA5054C08:F6198      | 138  | 50 | \$9.29   |
| NSA5357-10-32:F6198   | 30   | 20 | \$141.30 |
| NSA5399-9-20A:F6198   | 186  | 50 | \$160.31 |
| NSA5477VHK8-42:F6198  | 2    | 50 | \$644.32 |
| NSA5532C1037:F6198    | 9    | 50 | \$63.94  |
| ABS0114V6-15:FAPE3    | 480  | 50 | \$3.57   |
| ABS1115A020D450:FAPE3 | 71   | 50 | \$18.70  |
| ABS1623CB4E:FAPE3     | 275  | 50 | \$5.39   |
| AS3582-008:81343      | 3291 | 50 | \$2.25   |
| ASNA2394E9:F6198      | 16   | 50 | \$10.78  |
| ASNA2705-3K12:F6198   | 181  | 50 | \$279.04 |
| EN2997RS60803B6:I9005 | 23   | 50 | \$62.43  |
| EN2997SE01831BN:I9005 | 20   | 50 | \$73.14  |
| EN6114T3X10:I9005     | 206  | 50 | \$28.91  |
| NAS6403A10:80205      | 67   | 20 | \$5.99   |
| NSA5030-3-32:F6198    | 250  | 20 | \$18.45  |
| NSA5089V4-10:F6198    | 1922 | 50 | \$2.85   |
| NSA5478BV10-25:F6198  | 2    | 50 | \$911.04 |
| ABS0113-10-22X:FAPE3  | 17   | 50 | \$164.45 |
| ABS0395C5-12M:FAPE3   | 9    | 50 | \$137.82 |
| ABS1114D028B200:FAPE3 | 14   | 50 | \$33.35  |
| AN814-10DL:88044      | 77   | 50 | \$9.82   |
| AN924-8J:88044        | 5    | 50 | \$6.63   |
| ASNA2001V4-12X:F6198  | 129  | 50 | \$80.05  |
| E0219ASUUU:F5442      | 93   | 20 | \$8.31   |
| EN2997RS60803AN:H1822 | 50   | 50 | \$34.11  |
| HL633-6-20:92215      | 235  | 50 | \$4.72   |
| MS17825-10:96906      | 60   | 20 | \$3.74   |
| NAS1306-52:80205      | 110  | 20 | \$2.06   |
| NAS6703HU8:80205      | 7    | 20 | \$81.20  |
| NAS7503U6:80205       | 249  | 50 | \$1.35   |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| NSA5368E616A:F6198    | 565   | 50 | \$1.07   |
| NSA8140-05LK:F6198    | 8     | 20 | \$94.86  |
| ABS0107T250:FAPE3     | 14    | 50 | \$146.89 |
| BLT5563:K0680         | 11    | 50 | \$64.04  |
| E0053R10B6PNF:F5442   | 194   | 20 | \$27.71  |
| E0237E15P01A:F5442    | 67    | 30 | \$15.61  |
| EN3155-003F2020:I9005 | 240   | 50 | \$0.38   |
| EN6114-9Y27:I9005     | 50    | 50 | \$187.23 |
| EN6114L5-18:I9005     | 2     | 20 | \$53.80  |
| EN6115K5-18:I9005     | 426   | 30 | \$2.64   |
| MS25440-4A:96906      | 485   | 20 | \$0.63   |
| MS9556-26:96906       | 20    | 50 | \$6.14   |
| NAS1149GN532P:80205   | 1262  | 50 | \$0.38   |
| NSA5191-3V75:F6198    | 35    | 20 | \$33.72  |
| NSA5350-4-16:F6198    | 3     | 50 | \$157.82 |
| ABS0114T3-33:FAPE3    | 933   | 50 | \$5.73   |
| ABS0218-3-9:FAPE3     | 4350  | 50 | \$0.75   |
| ABS1358-10-09C:FAPE3  | 45    | 50 | \$91.21  |
| HL755VF8-9:92215      | 166   | 20 | \$24.37  |
| M25988-1-331:81349    | 38    | 20 | \$11.86  |
| MS20426D3-5:96906     | 10129 | 30 | \$0.03   |
| MS20470DD6-9D:96906   | 8200  | 50 | \$0.07   |
| MS21140S0507:96906    | 30    | 50 | \$5.01   |
| NAS1131-3:80205       | 1058  | 50 | \$0.87   |
| NAS1131-7:80205       | 350   | 50 | \$1.68   |
| NAS1802-3-23:80205    | 995   | 50 | \$1.00   |
| NAS514P440-7P:80205   | 7965  | 50 | \$0.05   |
| NAS6604-6X:80205      | 587   | 50 | \$24.16  |
| NSA5089-3-2:F6198     | 268   | 20 | \$1.80   |
| NSA5089-7D17:F6198    | 84    | 30 | \$10.67  |
| NSA5476BV6-9:F6198    | 4     | 20 | \$181.60 |
| ABS5483-5-001:FAPE3   | 6     | 50 | \$123.72 |
| AN386-2-7:88044       | 219   | 50 | \$6.37   |
| DAN7-14-20:D8518      | 65    | 20 | \$61.90  |
| HLT912BV10-22:73197   | 388   | 50 | \$8.65   |
| M8791-1-022:96906     | 316   | 20 | \$0.73   |
| MS20470DD7-8:96906    | 60    | 20 | \$0.55   |
| MS24677-2:96906       | 730   | 20 | \$1.17   |
| NSA5031-3-18:F6198    | 978   | 50 | \$3.43   |
| ABS0114T4-15:FAPE3    | 28    | 50 | \$2.70   |
| E0178-02:F5442        | 1     | 50 | \$172.50 |
| EN6114B5-5:I9005      | 510   | 50 | \$2.94   |
| HLT912BV8-22:73197    | 771   | 50 | \$8.93   |
| LN9198-3208B:D8442    | 53400 | 50 | \$0.12   |
| MS24693S274:96906     | 7469  | 50 | \$0.16   |
| NAS1100-4-12:80205    | 880   | 20 | \$2.07   |
| NAS1351N4-24:80205    | 49    | 20 | \$2.66   |
| NSA5031-5-38:F6198    | 224   | 20 | \$13.16  |
| NSA5359-5-8:F6198     | 74    | 50 | \$18.46  |
| SL40110P:97393        | 21    | 50 | \$316.37 |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| ABS1114B016D530:FAPE3 | 10    | 50 | \$139.41 |
| ABS5642AER29-8:FAPE3  | 103   | 50 | \$2.02   |
| E0545F21-35YC:F6198   | 26    | 20 | \$28.13  |
| EN3660-005N28B:I9005  | 99    | 20 | \$67.32  |
| EN6115-3X6:I9005      | 106   | 50 | \$82.83  |
| HL112VAZ6-8:73197     | 130   | 50 | \$3.98   |
| HLT908PB10-18:F0188   | 9     | 20 | \$92.17  |
| MS24694C70:96906      | 360   | 50 | \$0.77   |
| MS90354S0602:96906    | 180   | 50 | \$2.59   |
| NAS1149FN532P:80205   | 27980 | 50 | \$0.05   |
| NAS1305-36:80205      | 50    | 50 | \$1.27   |
| NAS1790-3R18:80205    | 530   | 50 | \$1.18   |
| NAS561P4-10:80205     | 2000  | 20 | \$0.19   |
| NAS6204-32:80205      | 200   | 30 | \$1.57   |
| NSA5042C05A160:F6198  | 425   | 20 | \$8.48   |
| NSA5398-12A38:F6198   | 100   | 50 | \$168.34 |
| NSA5482PN10-40:F6198  | 271   | 50 | \$90.76  |
| EN3545E05FXA00A:I9005 | 27    | 50 | \$44.43  |
| EN4537-2D10T018:I9005 | 61    | 50 | \$57.35  |
| EN6114T2-10:I9005     | 607   | 50 | \$3.90   |
| NAS1351N4-12:80205    | 790   | 50 | \$1.69   |
| NAS1669-5L7:80205     | 80    | 50 | \$84.07  |
| NAS509L6C:80205       | 133   | 50 | \$11.22  |
| NAS6605D32:80205      | 400   | 30 | \$2.78   |
| NSA5154V8-28:F6198    | 4     | 50 | \$453.98 |
| ABS0114T3-46:FAPE3    | 926   | 50 | \$9.34   |
| ASNA2537-7:F6198      | 1401  | 50 | \$6.03   |
| D205-12A12:F6101      | 114   | 20 | \$310.42 |
| DIN84M4X5A2:D8286     | 215   | 50 | \$0.55   |
| EN2997SE01203FN:I9005 | 1     | 50 | \$67.76  |
| EN6129C08-13H:I9005   | 136   | 50 | \$5.66   |
| MS14183LC10:96906     | 32    | 20 | \$34.31  |
| MS21140U0804W:96906   | 4     | 50 | \$50.76  |
| MS27039-4-09:96906    | 1080  | 50 | \$0.26   |
| NAS1149D1416K:80205   | 3630  | 50 | \$0.36   |
| NAS1306-16:80205      | 36    | 50 | \$3.33   |
| NAS6605D23:80205      | 189   | 50 | \$3.76   |
| NSA5042-08-435:F6198  | 9     | 50 | \$47.77  |
| NSA5088-4-16:F6198    | 46    | 50 | \$24.08  |
| NSA5149C4A:F6198      | 66    | 50 | \$17.79  |
| NSA5359-5-7:F6198     | 97    | 50 | \$132.60 |
| NSA5398-5-16A:F6198   | 25    | 50 | \$153.79 |
| NSA5399-5-18A:F6198   | 44    | 50 | \$154.82 |
| PLT215-8-4:92215      | 221   | 50 | \$6.18   |
| SP126E:K5640          | 2482  | 50 | \$0.30   |
| ABS1745K4-10:FAPE3    | 100   | 50 | \$226.25 |
| ASNA0093-4-7:F6198    | 843   | 50 | \$16.05  |
| ASNA2352T5-11:F6198   | 248   | 20 | \$20.33  |
| E0248A2-6H4R:F5442    | 1780  | 50 | \$0.24   |
| EN6115B12Y32:I9005    | 10    | 50 | \$395.13 |



|                       |       |    |            |
|-----------------------|-------|----|------------|
| MS14104-5:96906       | 69    | 50 | \$14.60    |
| MS21073-04:96906      | 5125  | 50 | \$0.90     |
| NAS1096-1-3:80205     | 1087  | 20 | \$0.74     |
| NAS1242D4-12:80205    | 80    | 20 | \$0.36     |
| NAS1306-6:80205       | 160   | 50 | \$1.65     |
| NAS6703-13:80205      | 657   | 50 | \$1.11     |
| NSA5482PN10-24:F6198  | 46    | 50 | \$138.04   |
| ABS1028E00EA487:FAPE3 | 5     | 50 | \$2,677.08 |
| ASNA2048-2-05:F6198   | 80    | 50 | \$1.18     |
| E0186R22P19-08F:F5442 | 11    | 30 | \$47.61    |
| EN3645F6GQ75AN:I9005  | 7     | 50 | \$261.84   |
| MBF2113S7-200:92215   | 10    | 20 | \$70.42    |
| NAS6203-3D:80205      | 420   | 50 | \$1.37     |
| A228Q30X:K7766        | 9     | 50 | \$433.31   |
| E0362F15P03A:F5442    | 20    | 50 | \$25.88    |
| EN6115T10-31:I9005    | 242   | 50 | \$47.38    |
| HST720CG16-19:73197   | 6     | 50 | \$84.65    |
| MS20470D6-4:96906     | 5925  | 50 | \$0.05     |
| MS24694S110:96906     | 461   | 50 | \$1.51     |
| NAS6605-7Y:80205      | 16    | 20 | \$14.89    |
| NAS6703D7:80205       | 34    | 50 | \$13.08    |
| NSA5305-8E:F6198      | 997   | 50 | \$8.37     |
| NSA5479BV4-11Y:F6198  | 91    | 50 | \$7.50     |
| NSA5532-768:F6198     | 1     | 50 | \$249.45   |
| ABS0787B55C:FAPE3     | 6     | 50 | \$9.66     |
| ABS1380-18M1216:FAPE3 | 88    | 50 | \$12.01    |
| EN6115-7-27:I9005     | 75    | 50 | \$9.64     |
| HL70TW5:92215         | 262   | 50 | \$2.16     |
| HLT900BV14-15:73197   | 3     | 50 | \$75.30    |
| MS20392-2R7:96906     | 50    | 20 | \$17.35    |
| MS9566-13:96906       | 277   | 50 | \$3.69     |
| NAS1153V16A:80205     | 43    | 20 | \$9.68     |
| NAS6704-19:80205      | 95    | 50 | \$9.91     |
| NSA5020-06-5:F6198    | 185   | 50 | \$3.84     |
| NSA5153V6-24:F6198    | 5     | 50 | \$406.86   |
| NSA5356-4-7:F6198     | 56    | 20 | \$13.95    |
| ABS0389A5-2-1:FAPE3   | 109   | 50 | \$89.21    |
| ABS0951B3LP023:FAPE3  | 2     | 50 | \$449.16   |
| ASNA0123-10-16:F6198  | 47    | 50 | \$62.07    |
| E0199-03-16K:F6198    | 38    | 20 | \$101.64   |
| E0545F09-35YN:F6198   | 6     | 50 | \$54.19    |
| EN6069T3-05:I9005     | 109   | 50 | \$48.39    |
| HST11BJ8-7:F0188      | 158   | 20 | \$4.02     |
| HST12AP8-6:73197      | 7     | 20 | \$80.50    |
| MS35338-135:96906     | 40353 | 50 | \$0.14     |
| NAS1792C4-1:F0188     | 398   | 50 | \$1.65     |
| NSA5357-3-12:F6198    | 98    | 50 | \$47.88    |
| NSA5359-3-11:F6198    | 89    | 50 | \$4.46     |
| NSA5527-06-01:F6198   | 48    | 50 | \$0.60     |
| ABS1265A010BA00:FAPE3 | 12    | 50 | \$57.04    |

|                       |       |    |          |
|-----------------------|-------|----|----------|
| E0418M018E:F5442      | 2     | 50 | \$235.47 |
| HL62PB10-16:F0188     | 54    | 50 | \$10.09  |
| M819341-08C006P:81349 | 50    | 20 | \$54.52  |
| NAS1097D6-11:80205    | 10564 | 20 | \$0.07   |
| NAS6605-42:80205      | 30    | 20 | \$1.66   |
| NSA5030-4-14:F6198    | 70    | 50 | \$19.37  |
| NSA5031-7D42:F6198    | 279   | 50 | \$22.06  |
| NSA855120-22D:F6198   | 50    | 50 | \$49.15  |
| ABS0256-6-400:FAPE3   | 4     | 50 | \$38.95  |
| ABS0582V21-09P:FAPE3  | 9     | 50 | \$29.09  |
| ABS1700AF0813XB:FAPE3 | 50    | 50 | \$690.93 |
| ABS2057B052-02:FAPE3  | 10    | 50 | \$126.73 |
| ASNA2314-3C6:F6198    | 22    | 20 | \$31.04  |
| DAN7-12-11:D8518      | 22    | 50 | \$6.07   |
| E0681-01:F5442        | 6     | 50 | \$177.37 |
| EN6115V5Y5:I9005      | 24    | 50 | \$87.76  |
| MS27039-1-15:96906    | 3261  | 50 | \$0.21   |
| NAS1102E06-7P:80205   | 150   | 50 | \$0.61   |
| NAS1153-10D:80205     | 100   | 20 | \$3.23   |
| NAS1515H5:80205       | 8542  | 50 | \$0.20   |
| NSA5153V9-23:F6198    | 10    | 50 | \$182.48 |
| NSA5479BV3-11:F6198   | 1750  | 50 | \$28.81  |
| PFSC3-1-2-38A:F0304   | 70    | 50 | \$63.31  |
| EN3545D09MXA00A:I9005 | 1     | 50 | \$88.10  |
| HL12VF10-5:92215      | 105   | 20 | \$5.97   |
| MS21915D10-6:96906    | 7     | 20 | \$23.63  |
| MS27039C0812:96906    | 1177  | 50 | \$0.45   |
| MS9276-09:96906       | 5288  | 50 | \$0.73   |
| NAS1242D5-6:80205     | 1000  | 50 | \$0.07   |
| NAS1726-3D:80205      | 437   | 50 | \$1.12   |
| NSA5356-8-18:F6198    | 100   | 50 | \$51.39  |
| NSA5398-10A42:F6198   | 70    | 50 | \$211.63 |
| NSA5478BV3-16:F6198   | 920   | 50 | \$2.61   |
| ABS1153A05-65:FAPE3   | 3     | 50 | \$11.02  |
| AS1038J0606:81343     | 34    | 50 | \$16.66  |
| ASNA2001T7-17:F6198   | 248   | 50 | \$32.94  |
| EN6115B2E8:I9005      | 1131  | 50 | \$1.38   |
| HLT901BV20-32:73197   | 10    | 50 | \$74.17  |
| MS20426D5-4:96906     | 12375 | 50 | \$0.03   |
| MS27039-0810:96906    | 7157  | 50 | \$0.18   |
| NAS6703U7X:80205      | 21    | 50 | \$61.86  |
| NAS6704DU27:80205     | 577   | 20 | \$16.02  |
| NSA5357-10-22:F6198   | 35    | 20 | \$146.36 |
| NSA5359-6-13:F6198    | 11    | 20 | \$162.42 |
| NSA5477BV4-3:F6198    | 1440  | 20 | \$20.59  |
| ABS0114V8-30:FAPE3    | 18    | 50 | \$61.95  |
| AN565C6H12:88044      | 7     | 50 | \$34.41  |
| AS5179D10:81343       | 50    | 20 | \$7.40   |
| ASNA0092P5-22:F6198   | 38    | 50 | \$20.42  |
| ASNA2157-03:F6198     | 241   | 50 | \$23.35  |



|                       |       |    |            |
|-----------------------|-------|----|------------|
| EN6069KE5X07:I9005    | 3042  | 50 | \$1.53     |
| HL110VF8-2:92215      | 11    | 50 | \$5.34     |
| MS21093-0835:96906    | 1030  | 20 | \$0.24     |
| MS29513-151:96906     | 135   | 50 | \$1.34     |
| MS90354U0609:96906    | 320   | 50 | \$3.54     |
| NAS1197-6:80205       | 1799  | 50 | \$0.09     |
| NAS1304-38D:80205     | 154   | 20 | \$1.96     |
| NSA5357-10-30:F6198   | 2     | 20 | \$259.05   |
| ABS0213-6-5R:FAPE3    | 23    | 50 | \$7.26     |
| ABS0560VHK16-50:FAPE3 | 42    | 50 | \$208.55   |
| ASNA2394EW3:F6198     | 886   | 50 | \$15.63    |
| ASNA2397JD716:F6198   | 12505 | 50 | \$0.12     |
| MBF2113S6-200:92215   | 3     | 20 | \$13.14    |
| MS35842-11:96906      | 387   | 50 | \$2.76     |
| NAS1203-14:80205      | 1250  | 50 | \$0.21     |
| NAS77A9-034N:80205    | 23    | 20 | \$98.94    |
| NSA5353D10C:F6198     | 59    | 20 | \$5.27     |
| NSA5479BV5-21X:F6198  | 9     | 50 | \$52.24    |
| ASNA2001V3-14X:F6198  | 47    | 50 | \$110.63   |
| ASNA2012V6-20:F6198   | 2     | 50 | \$1,069.34 |
| ASNA2123-05X:F6198    | 100   | 50 | \$22.75    |
| DIN65399-2407BF:D8286 | 92800 | 50 | \$0.03     |
| EN4537-2F08T012:I9005 | 75    | 50 | \$39.19    |
| NAS4403-4:80205       | 1800  | 20 | \$0.22     |
| NAS6603H23:80205      | 12    | 20 | \$21.43    |
| NSA5479BV4-7:F6198    | 1294  | 50 | \$16.89    |
| NSA5479BV5-4:F6198    | 844   | 50 | \$37.24    |
| 1604S41-130BP:71286   | 90    | 50 | \$16.10    |
| EN6069KE5X09:I9005    | 944   | 50 | \$10.97    |
| EN6101KE6X07:I9005    | 199   | 20 | \$7.02     |
| HL113VF10-9:92215     | 41    | 20 | \$14.05    |
| HL411VF8-14:92215     | 900   | 20 | \$1.56     |
| HL855VF8-4:C4293      | 150   | 20 | \$19.60    |
| HLT924BV12-9:73197    | 57    | 50 | \$144.32   |
| MS51521B4S:96906      | 15    | 20 | \$40.77    |
| NAS1241D6-15:80205    | 185   | 20 | \$4.24     |
| NAS1581K3R14:80205    | 200   | 50 | \$37.47    |
| NAS1801-08-42:80205   | 274   | 50 | \$2.52     |
| NSA5023-4-17:F6198    | 22    | 50 | \$8.92     |
| NSA5191-3-23:F6198    | 182   | 50 | \$3.27     |
| NSA5399-16-80:F6198   | 47    | 20 | \$746.25   |
| NSA5476VHK7-21:F6198  | 47    | 50 | \$6.78     |
| NSA855033-24N:F6198   | 7     | 50 | \$387.08   |
| NAS1399M5-5:80205     | 70    | 50 | \$1.59     |
| NAS1103-4:80205       | 1067  | 50 | \$0.10     |
| NAS1352-3H8P:80205    | 161   | 50 | \$0.73     |
| MS21921-12J:96906     | 34    | 50 | \$73.46    |
| NSA5399-9-24A:F6198   | 172   | 50 | \$45.68    |
| ABS0951A0LP080:FAPE3  | 1     | 50 | \$174.31   |
| ABS0473-7:FAPE3       | 24    | 50 | \$42.91    |



|                       |       |    |          |
|-----------------------|-------|----|----------|
| EN6114-8X36:I9005     | 78    | 50 | \$23.88  |
| ABS0114V6D17:FAPE3    | 847   | 50 | \$2.23   |
| NSA5359-5-15:F6198    | 90    | 50 | \$5.90   |
| NAS6303U4X:80205      | 109   | 50 | \$50.32  |
| ABS0854-6-1:FAPE3     | 42    | 50 | \$19.22  |
| MS21908D10:96906      | 5     | 50 | \$47.78  |
| ASNA2551B01D01:F6198  | 176   | 50 | \$3.77   |
| HLT924BV16-19:73197   | 77    | 50 | \$24.43  |
| HLT901BV12-19:73197   | 4     | 50 | \$135.12 |
| ASNA2127-08C28:F6198  | 97    | 50 | \$13.81  |
| EN6114T3-18:I9005     | 3440  | 50 | \$1.25   |
| ABS0394B200:FAPE3     | 61    | 50 | \$3.61   |
| NAS1802-4-6:80205     | 29    | 50 | \$2.63   |
| NSA5042A05-225:F6198  | 202   | 50 | \$13.58  |
| AGS3781:U1653         | 570   | 50 | \$1.44   |
| MS9967-016:96906      | 82    | 50 | \$1.26   |
| MS21250-09018:96906   | 4     | 50 | \$20.24  |
| NAS6706D17:80205      | 96    | 50 | \$3.00   |
| ASNA2397KD6L:F6198    | 1655  | 50 | \$0.05   |
| MS25281F2:96906       | 77    | 50 | \$1.64   |
| NAS1833C08-500:80205  | 1220  | 50 | \$1.26   |
| ASNA2001V3-21:F6198   | 855   | 50 | \$3.60   |
| EN6114K10-32:I9005    | 218   | 50 | \$20.74  |
| ABS1115A012D650:FAPE3 | 96    | 50 | \$16.84  |
| NAS1100E04-7:80205    | 324   | 50 | \$0.24   |
| EN6114K8-24:I9005     | 467   | 50 | \$5.59   |
| MS17990C510:96906     | 94    | 50 | \$9.93   |
| ASNA2001T3-26:F6198   | 919   | 50 | \$12.08  |
| M83485-1-029:81349    | 360   | 50 | \$0.85   |
| ABS0744-48:FAPE3      | 24    | 50 | \$18.11  |
| MS17987C414:96906     | 54    | 50 | \$10.10  |
| NSA5713D1105:F6198    | 718   | 50 | \$0.75   |
| MS24665-1011:96906    | 1480  | 50 | \$0.02   |
| MS21913D3:96906       | 7     | 50 | \$4.19   |
| HL11VDF6-18:92215     | 850   | 50 | \$2.64   |
| AS2811-5-036:U1653    | 238   | 50 | \$1.06   |
| NSA8203-031:F6198     | 29    | 50 | \$3.40   |
| ABS0640-25A:FAPE3     | 48    | 50 | \$5.67   |
| ABS0785B08C:FAPE3     | 249   | 50 | \$3.71   |
| ASNA2328-3-24:F6198   | 465   | 50 | \$8.16   |
| E0486A01:F5442        | 1     | 50 | \$77.12  |
| ASNA0078A603X:F6198   | 180   | 50 | \$0.75   |
| MS14103-7P:96906      | 50    | 50 | \$11.89  |
| ABS0895-4-04:FAPE3    | 446   | 50 | \$4.63   |
| NAS8303-4:80205       | 13196 | 50 | \$0.17   |
| NAS1801-4-22:80205    | 242   | 50 | \$0.67   |
| ABS0787D127C:FAPE3    | 13    | 50 | \$4.83   |
| DAN8-8-15Y:D8518      | 30    | 50 | \$2.22   |
| E0088-10-304NN:F5442  | 124   | 50 | \$1.08   |
| DAN316-3010:D8518     | 6220  | 50 | \$0.03   |



|                       |      |    |         |
|-----------------------|------|----|---------|
| NAS6607D20:80205      | 59   | 50 | \$4.43  |
| ABS1054A60801BN:FAPE3 | 22   | 50 | \$16.72 |
| NAS1801-08-15:80205   | 979  | 50 | \$0.16  |
| NAS1351N4-10:80205    | 335  | 50 | \$1.13  |
| NAS1611-230A:80205    | 420  | 50 | \$0.51  |
| NSA5159-41P:F6198     | 433  | 50 | \$9.98  |
| NSA5031-7D20:F6198    | 54   | 50 | \$18.45 |
| NSA937901C03:F6198    | 90   | 50 | \$5.60  |
| ABS1115A048D510:FAPE3 | 14   | 50 | \$19.62 |
| NAS1922-0175-3:80205  | 10   | 50 | \$4.26  |
| HL13V6-8:73197        | 4    | 50 | \$39.88 |
| NAS1102E3-28:80205    | 286  | 50 | \$0.71  |
| NSA5479BV8-18X:F6198  | 76   | 50 | \$18.99 |
| EN6115V3X19:I9005     | 80   | 50 | \$49.41 |
| NAS602-15P:80205      | 560  | 50 | \$0.11  |
| M27426-3128D:81349    | 160  | 50 | \$0.64  |
| ASNA2397D10:F6198     | 1800 | 50 | \$0.02  |
| HL410VF8-14:92215     | 520  | 50 | \$0.67  |
| NAS1149E0616P:80205   | 4481 | 50 | \$0.08  |
| MS35478-305:96906     | 180  | 50 | \$2.18  |
| AN525-10R12:88044     | 255  | 50 | \$0.12  |
| EN6114-16X43:I9005    | 198  | 50 | \$32.43 |
| HLT900BV6-5:92215     | 885  | 50 | \$2.09  |
| DAN8-5-11:D8518       | 25   | 50 | \$1.57  |
| HL111VF8-13:92215     | 270  | 50 | \$3.88  |
| ASNA2020-40-10:F6198  | 4271 | 50 | \$0.74  |
| NSA935807C04:F6198    | 669  | 50 | \$1.91  |
| NAS1834-3-500:80205   | 735  | 50 | \$1.09  |
| ABS0638C10:FAPE3      | 90   | 50 | \$2.97  |
| NAS1288-4:80205       | 671  | 50 | \$3.28  |
| NAS1836-3-09:80205    | 898  | 50 | \$0.49  |
| MS20392-13C41:96906   | 30   | 50 | \$1.07  |
| NAS6206-92D:80205     | 639  | 50 | \$15.00 |
| NSA938192FC0801:F6198 | 25   | 50 | \$4.06  |
| NSA5477VHK6-17:F6198  | 11   | 50 | \$49.04 |
| ABS0114T6-22:FAPE3    | 98   | 50 | \$4.31  |
| ABS0114V6D13:FAPE3    | 509  | 50 | \$1.27  |
| HL10V5-5:73197        | 64   | 50 | \$1.29  |
| NSA5353D10B:F6198     | 2554 | 50 | \$1.26  |
| D38999-26FA98SN:F1983 | 3    | 50 | \$19.65 |
| ASNA2051DXJ5640:F6198 | 76   | 50 | \$15.81 |
| MS21209F5-25L:51563   | 2856 | 50 | \$0.24  |
| DAN5-10-15Y:D8518     | 6    | 50 | \$45.73 |
| E0684S12FSN:F5442     | 5    | 50 | \$21.52 |
| MS20392-3R25:96906    | 24   | 50 | \$6.10  |
| NSA5023-4D13:F6198    | 16   | 50 | \$31.90 |
| ABS0060-212:FAPE3     | 11   | 50 | \$4.74  |
| ABS0114T4-14:FAPE3    | 402  | 50 | \$1.08  |
| ABS0114-7D43X:FAPE3   | 295  | 50 | \$68.58 |
| ABS0114T3-20:FAPE3    | 1923 | 50 | \$1.62  |

|                       |       |    |          |
|-----------------------|-------|----|----------|
| 4807-0407:U1595       | 574   | 50 | \$0.46   |
| 295RTW3BYY02:F0214    | 8     | 50 | \$647.42 |
| ABS0060-231:FAPE3     | 6     | 50 | \$10.40  |
| EN6115V6X3:I9005      | 64    | 50 | \$34.82  |
| EN6115T8-26:I9005     | 66    | 50 | \$6.21   |
| NSA5042C07A305:F6198  | 493   | 50 | \$10.20  |
| VLC1380-5:92215       | 2769  | 50 | \$0.50   |
| MGG8301-92:D2696      | 42    | 50 | \$4.80   |
| NSA5357-3-11:F6198    | 95    | 50 | \$3.05   |
| EN2997SE00803D6:I9005 | 5     | 50 | \$29.36  |
| MS17987C535:96906     | 80    | 50 | \$11.09  |
| ABS0114V5-32:FAPE3    | 136   | 50 | \$2.23   |
| NSA5039-08-1:F6198    | 2295  | 50 | \$3.71   |
| NAS1921C04S06U:80205  | 840   | 50 | \$1.40   |
| NSA5368E616C:F6198    | 773   | 50 | \$2.06   |
| NAS6403A4:80205       | 1563  | 50 | \$1.34   |
| ASNA0009-033:F6198    | 741   | 50 | \$0.31   |
| MBF2112S6-350:92215   | 375   | 50 | \$19.06  |
| MS122907:96906        | 1080  | 50 | \$0.34   |
| HL11VAZ8-23:73197     | 33    | 50 | \$2.89   |
| NAS6203-4D:80205      | 60    | 50 | \$0.72   |
| 2700-8:D0680          | 59    | 50 | \$4.53   |
| EN6115-4-10:I9005     | 3015  | 50 | \$1.44   |
| MBBN4477-4012:D8518   | 951   | 50 | \$0.04   |
| NSA5040V4-10:F6198    | 135   | 50 | \$0.54   |
| ASNA2051DCJ3209:F6198 | 37600 | 50 | \$0.02   |
| ASNA2314-4-5:F6198    | 57    | 50 | \$24.37  |
| NAS1306-12:80205      | 240   | 50 | \$0.46   |
| NSA937901RB0110:F6198 | 45    | 50 | \$7.36   |
| MS20613-3C4:96906     | 4260  | 50 | \$0.04   |
| EN6114K6X31:I9005     | 190   | 50 | \$34.01  |
| MS20470A4-7:96906     | 4677  | 50 | \$0.08   |
| NAS6205-6:80205       | 275   | 50 | \$0.63   |
| NAS1801-3D7:80205     | 48    | 50 | \$1.13   |
| NSA5516C35NF:F6198    | 125   | 50 | \$2.12   |
| EN6114K7X32:I9005     | 59    | 50 | \$66.57  |
| NSA5358-4-15:F6198    | 196   | 50 | \$22.51  |
| NSA5378-8-12:F6198    | 2     | 50 | \$33.47  |
| EN6114K7X31:I9005     | 14    | 50 | \$40.53  |
| EN6114T8X24:I9005     | 7     | 50 | \$199.17 |
| NSA939526-13C:F6198   | 8     | 50 | \$9.71   |
| NSA5476VHK5-11:F6198  | 460   | 50 | \$0.75   |
| ASNA2001T5-5:F6198    | 485   | 50 | \$3.96   |
| ASNA2049DEJ4815:F6198 | 225   | 50 | \$1.03   |
| E0080-01-16C:F5442    | 184   | 50 | \$7.63   |
| EN6115-3-20:I9005     | 6     | 50 | \$65.01  |
| MBF2110S6-300:98524   | 80    | 50 | \$13.25  |
| MS21122-14:96906      | 30    | 50 | \$4.34   |
| MS21299C7:96906       | 1313  | 50 | \$0.60   |
| MS24665-82:96906      | 18729 | 50 | \$0.08   |



|                       |      |    |         |
|-----------------------|------|----|---------|
| MS51957-35:96906      | 550  | 50 | \$0.44  |
| MS51960-67:96906      | 950  | 30 | \$0.14  |
| NAS1101E4-8:80205     | 44   | 20 | \$1.59  |
| NAS4403-10:80205      | 421  | 50 | \$0.29  |
| NSA5359-8-38:F6198    | 88   | 50 | \$55.72 |
| EN3646A01210AN:I9005  | 87   | 50 | \$6.71  |
| EN6115-6X17:I9005     | 81   | 50 | \$24.76 |
| HL110VAZ6-5:73197     | 114  | 30 | \$0.58  |
| MS21083D3:96906       | 462  | 30 | \$0.14  |
| MS21916J6-5:96906     | 64   | 30 | \$3.06  |
| MS21919WCF4:96906     | 747  | 20 | \$0.23  |
| MS24693-273B:96906    | 1359 | 20 | \$0.04  |
| MS35336-17:96906      | 323  | 50 | \$1.69  |
| MS9592-020:96906      | 480  | 50 | \$0.67  |
| MS9966-05:96906       | 190  | 20 | \$0.38  |
| NAS1100E04-8:80205    | 2900 | 20 | \$0.04  |
| NAS1993-1T:80205      | 266  | 20 | \$0.17  |
| NAS626-16:80205       | 164  | 20 | \$11.23 |
| NAS6304U20D:80205     | 5    | 20 | \$11.78 |
| NSA5042-160-800:F6198 | 25   | 20 | \$20.04 |
| NSA5359-8-22:F6198    | 13   | 50 | \$27.40 |
| NSA5478VHK5-13:F6198  | 142  | 50 | \$29.50 |
| NSA5479BV5-8Y:F6198   | 7    | 50 | \$24.53 |
| ABS0114V3-3X:FAPE3    | 13   | 50 | \$16.09 |
| ABS1152-003AFC:FAPE3  | 995  | 50 | \$11.05 |
| ABS1322T12:FAPE3      | 19   | 50 | \$81.94 |
| AS48026:U1653         | 101  | 20 | \$0.86  |
| AS62521:U1653         | 5    | 20 | \$63.41 |
| ASNA0077A507:F6198    | 618  | 20 | \$0.23  |
| ASNA3752G202010:F6198 | 17   | 20 | \$70.00 |
| EN6069KE5-08-5:I9005  | 8176 | 50 | \$0.56  |
| EN6115-6-18:I9005     | 366  | 50 | \$7.01  |
| HL741VF6-11:92215     | 300  | 50 | \$5.47  |
| MS16562-50:96906      | 950  | 50 | \$0.12  |
| MS20615-3M3:96906     | 3169 | 50 | \$0.03  |
| MS35207-268:96906     | 2723 | 50 | \$0.18  |
| NAS1149D1016K:80205   | 3411 | 20 | \$0.08  |
| NAS1515H6:80205       | 5653 | 50 | \$0.15  |
| NAS6204-34:80205      | 133  | 50 | \$1.09  |
| NAS6704H7:80205       | 77   | 50 | \$2.74  |
| NAS6803U7:80205       | 721  | 20 | \$0.70  |
| NSA5478VHK6-15:F6198  | 12   | 50 | \$23.90 |
| NSA855111D6:F6198     | 99   | 50 | \$41.04 |
| DAN9-5-6:D8518        | 150  | 20 | \$0.29  |
| E0088-40-100:F5442    | 392  | 20 | \$0.18  |
| HLT924BJ6-6:73197     | 30   | 20 | \$11.99 |
| HW51130-4K7:K6405     | 22   | 50 | \$4.42  |
| MS14102-6P:96906      | 27   | 30 | \$8.08  |
| MS20470D6-11:96906    | 1478 | 30 | \$0.04  |
| MS20470E6-7:96906     | 3895 | 50 | \$0.30  |

|                       |       |    |          |
|-----------------------|-------|----|----------|
| MS21056L4:96906       | 346   | 50 | \$1.47   |
| MS21061L5:96906       | 70    | 20 | \$1.67   |
| MS51959-42:96906      | 1517  | 20 | \$0.02   |
| NAS1153E17P:80205     | 385   | 20 | \$0.31   |
| NAS1352C08H4:80205    | 703   | 20 | \$0.40   |
| NAS509-18:92595       | 80    | 20 | \$4.14   |
| NSA5476BV4-14:F6198   | 1982  | 50 | \$22.17  |
| ABS1153E080805:FAPE3  | 9     | 50 | \$6.43   |
| ASNA2051DCJ2448:F6198 | 356   | 50 | \$0.89   |
| ASNA2722F3-10:F6198   | 105   | 20 | \$0.27   |
| EN2997KE3C14:I9005    | 3     | 30 | \$20.41  |
| LN9198-2408BF:D8442   | 64036 | 30 | \$0.01   |
| MS9058-08:96906       | 798   | 20 | \$0.19   |
| NAS1097U3-3:80205     | 2957  | 20 | \$0.12   |
| NAS7403-5:80205       | 1371  | 50 | \$0.15   |
| NAS8703U1:80205       | 384   | 50 | \$0.52   |
| NSA5356-3-8:F6198     | 34    | 50 | \$35.72  |
| NSA5368-616A:F6198    | 620   | 50 | \$0.99   |
| ASNA2721N08-4:F6198   | 587   | 50 | \$3.89   |
| EN6101KE7-09:I9005    | 70325 | 50 | \$0.09   |
| EN6114K7X5:I9005      | 730   | 20 | \$4.43   |
| EN6115K10-34:I9005    | 247   | 50 | \$15.09  |
| EN6115K7Y21:I9005     | 9     | 50 | \$40.09  |
| MS21254-5RL:96906     | 50    | 20 | \$1.36   |
| MS9201-05:96906       | 12    | 50 | \$6.59   |
| MS9565-08:96906       | 123   | 30 | \$1.00   |
| NAS1398D6-5:80205     | 162   | 20 | \$0.23   |
| NAS1399D5-2:80205     | 615   | 50 | \$1.20   |
| NSA5030-4-26:F6198    | 135   | 50 | \$2.38   |
| NSA5030-4D23:F6198    | 117   | 50 | \$4.10   |
| NSA5398-4-9A:F6198    | 9     | 20 | \$60.25  |
| NSA8205-251:F6198     | 67    | 30 | \$4.08   |
| 55027004-1:K0680      | 8     | 50 | \$238.86 |
| DAN239-19:D8518       | 21    | 50 | \$3.43   |
| EN6081D4X08:I9005     | 1896  | 20 | \$0.43   |
| EN6114-10Y30:I9005    | 33    | 20 | \$39.31  |
| MS27641-6:96906       | 40    | 50 | \$10.02  |
| NAS1096-2-27:80205    | 960   | 20 | \$0.09   |
| NAS1149DN316K:80205   | 11375 | 50 | \$0.06   |
| NAS1156-9:80205       | 238   | 50 | \$2.67   |
| NAS1351C08-6:80205    | 24    | 50 | \$3.96   |
| NAS6308-20D:80205     | 13    | 50 | \$17.38  |
| NSA5378A5-11:F6198    | 987   | 50 | \$16.30  |
| NSA5477VHK6-18:F6198  | 985   | 20 | \$3.95   |
| NSA5479BV5-12X:F6198  | 58    | 20 | \$9.43   |
| SL602-3-375C:97393    | 92    | 20 | \$1.14   |
| ASNA2397KD6:F6198     | 2200  | 20 | \$0.02   |
| ASNA3757G242410:F6198 | 9     | 20 | \$55.70  |
| DAN169E3-25:D8518     | 184   | 50 | \$2.05   |
| EN6114K12Y19:I9005    | 1     | 20 | \$901.07 |



|                       |      |    |          |
|-----------------------|------|----|----------|
| EN6114K7X34:I9005     | 89   | 50 | \$264.29 |
| HL112VAZ6-2:73197     | 85   | 20 | \$6.34   |
| MS20470AD4-12:96906   | 297  | 20 | \$0.15   |
| MS21919WDF4:96906     | 206  | 20 | \$0.20   |
| NSA5357-4-9:F6198     | 16   | 50 | \$16.97  |
| NSA5479BV7-13X:F6198  | 96   | 50 | \$23.73  |
| NSA931321-500A:F6198  | 2    | 50 | \$28.38  |
| NSA939511-03C:F6198   | 343  | 50 | \$0.21   |
| E0091-40-160NN:F5442  | 168  | 50 | \$2.96   |
| MS17987C407:96906     | 29   | 50 | \$11.84  |
| MS21902W10:96906      | 12   | 50 | \$6.89   |
| MS29561-214:96906     | 3149 | 50 | \$0.31   |
| NAS1096-2-3:80205     | 2013 | 20 | \$0.03   |
| NAS1101-5-25:80205    | 58   | 50 | \$8.65   |
| NAS6704DU44:80205     | 100  | 20 | \$0.95   |
| NSA5478BV10-16:F6198  | 2    | 20 | \$33.11  |
| NSA5478VHK6-22:F6198  | 151  | 50 | \$65.95  |
| EN3646A01412AW:I9005  | 16   | 20 | \$2.50   |
| EN3646RS62039BX:I9005 | 92   | 20 | \$4.30   |
| EN6114T7-12:I9005     | 207  | 50 | \$2.70   |
| EN6115K7Y24:I9005     | 136  | 50 | \$50.91  |
| NAS1102V3-8:80205     | 928  | 30 | \$0.29   |
| NAS1149C2090R:80205   | 190  | 50 | \$0.82   |
| NAS1738M5-6:80205     | 303  | 50 | \$1.14   |
| NAS578-9B:80205       | 120  | 50 | \$2.35   |
| NSA5031-4D21:F6198    | 478  | 30 | \$6.84   |
| NSA5414-40-08:F6198   | 110  | 20 | \$0.27   |
| NSA855140-15C:F6198   | 101  | 50 | \$24.24  |
| EN6114-12X37:I9005    | 124  | 20 | \$28.71  |
| HLT924BV6-2:73197     | 30   | 50 | \$32.79  |
| M85052-2-5:81349      | 60   | 30 | \$1.25   |
| MS21076L08:96906      | 588  | 50 | \$0.44   |
| MS21106-12:96906      | 129  | 20 | \$1.66   |
| MS28775-236:96906     | 740  | 50 | \$0.54   |
| MS35214-29:96906      | 730  | 50 | \$0.18   |
| NAS1801-4-23:80205    | 403  | 20 | \$0.25   |
| NAS1919B04-06:80205   | 366  | 20 | \$0.65   |
| NAS6606-15:80205      | 502  | 20 | \$0.22   |
| NAS9301E6-04:80205    | 280  | 50 | \$0.99   |
| NSA5121CR04-065:F6198 | 28   | 50 | \$1.49   |
| NSA5478VHK5-21:F6198  | 50   | 50 | \$55.09  |
| NSA5479BV4-8:F6198    | 562  | 50 | \$2.35   |
| AS3578-163:81343      | 65   | 50 | \$1.97   |
| DAN80A2-420:D8518     | 40   | 50 | \$6.69   |
| DHS781-62-16:U1598    | 425  | 50 | \$0.87   |
| MS9582-19:96906       | 67   | 20 | \$1.42   |
| NAS1751-08L6:80205    | 27   | 50 | \$12.76  |
| NAS1802-3D8:80205     | 30   | 50 | \$1.38   |
| SL210-3-1:97393       | 251  | 50 | \$0.55   |
| AN4H5A:88044          | 800  | 50 | \$0.56   |



|                      |       |    |          |
|----------------------|-------|----|----------|
| AN960D10L:88044      | 41071 | 50 | \$0.01   |
| AS3578-244:81343     | 212   | 30 | \$0.97   |
| DIN82004D1:D8286     | 1     | 20 | \$95.11  |
| E0090-48-180NN:F5442 | 286   | 20 | \$7.66   |
| MS9245-43:96906      | 182   | 50 | \$0.22   |
| NAS1635-04-5:80205   | 15967 | 50 | \$0.05   |
| NAS1720H4-5A:80205   | 121   | 50 | \$0.58   |
| NAS1790-3R11X:80205  | 94    | 20 | \$26.05  |
| NAS6605-18X:80205    | 96    | 50 | \$75.82  |
| NSA5444-44-020:F6198 | 222   | 20 | \$0.35   |
| NSA5488-8-20N:F6198  | 40    | 50 | \$126.15 |
| NSA855145-4C:F6198   | 248   | 50 | \$15.93  |
| ASNA2722B3-7:F6198   | 864   | 50 | \$1.07   |
| NAS1197-10:80205     | 10521 | 50 | \$0.06   |
| NAS6304U24:80205     | 65    | 50 | \$2.75   |
| NSA5042E05-338:F6198 | 37    | 50 | \$6.91   |
| ABS0114T6-25:FAPE3   | 70    | 50 | \$5.23   |
| M25988-1-011:81349   | 665   | 50 | \$0.23   |
| NAS1132-11:80205     | 4358  | 50 | \$0.21   |
| NAS604-3P:80205      | 168   | 50 | \$10.65  |
| NAS6608-16:80205     | 15    | 50 | \$4.18   |
| NSA5399-9-26:F6198   | 8     | 50 | \$44.42  |
| NSA5479BV5-16X:F6198 | 39    | 50 | \$35.33  |